



राष्ट्रीय राजधानी क्षेत्र, दिल्ली सरकार
लोक निर्माण विभाग
अधीक्षण अभियंता
पलाईओवर-5

रिंग रोड पलाईओवर के नीचे, विपरीत आई0 जी0 स्टेडियम गेट नं0 9, नई दिल्ली-110002
Under Ring Road Bypass Flyover, Opp. of IG Stadium Gate No.9, New Delhi-110002

Email: cpmpwddelhif5@gmail.com

Govt. of NCT of Delhi
Public Works Department
Superintending Engineer
Flyover- 5



सं0 23(10)/अधी.अभि./एफ-5/लो.नि.वि./2023-24/381

दिनांक 07/11/2023

निरीक्षण नोट

कार्य का नाम: Construction of flyover with Ramps, Footpath, Road work including Road Signage, Street Lights works, Drainage, Horticulture, Mural works 7 allied work at Road No. 56 between Anand Vihar ROB, and Apsara border ROB, New Delhi (EPC Mode).

करार संख्या- 02/EE/F-51/PWD/2022-23

एजेंसी:- M/s. GAWAR CONSTRUCTION LIMITED

The inspection of the above work was carried out by the undersigned on dated 03.11.23 in presence of following-

PWD Side: Sh. Rajan Mogha, Superintending Engineer, F-5
Sh. Sheikh Nizam, Assistant Engineer, F- 513


Agency Side: Shri Praveen Kaushik, Deputy Project Manager

During the inspection the following points were discussed:-

1. At various location of central verge extra construction material are lying needs to be removed on urgent basis for smooth movement of traffic.
2. Widening at start of flyover i.e. over Anand Vihar ROB towards Apsara border required expedite the work progress as due to narrow space available for traffic movement creates traffic jams.
3. Too many vehicles plying on wrong side leading to traffic jam, more marshalls to be deployed for smooth movement of traffic.
4. All around of working site needs to be barricaded & covered with green net.

5. All site staff / agency personnel should ensure for regular cleaning of road & water sprinkling to suppress dust.
6. GRAP-IV norms are implemented by Director (Technical) (Member & Convenor of Sub-Committee on GRAP) O/o Commission for Air Quality Management in National Capital Region and Adjoining Areas. It is directed that all measures are to be taken to control air pollution. Responsibility of any violation shall be of executing agency & EE should take action as per guidelines for any violation.
7. Zero tolerance policy should be taken against the other agencies working in the stretch.
8. Fines are to be imposed by AE-in-charge for each violation against the contractor or other Govt. agencies without fail under intimation to undersigned.
9. Agency to adhere to all safety guidelines as per agreement, CPWD Works Manual, Safety codes, Good structural engineering practices & as issued by GNCTD vide No. 4(60)/23-24/PWD-II/Roads (CD No. 057742583)/1054-47 dated 11.07.2023. Responsibility of any violation shall be of executing agency & EE should take action as per guidelines for any violation.


01/


(राजन मोघा)
अधीक्षण अभियंता

प्रतिलिपि सूचनार्थ प्रेषित:-

1. मुख्य अभियन्ता (फलाईओवर), लो.नि.वि., चौथा तल, एम.एस.ओ.भवन, नई दिल्ली।
2. कार्यपालक अभियन्ता, एफ-51, रिंग रोड फलाईओवर के नीचे, विपरीत आई.जी.आई. स्टेडियम गेट नं. 09, नई दिल्ली को सूचनार्थ एवं आवश्यक कार्यवाही हेतु।
3. सहायक अभियन्ता, एफ-513, लोक निर्माण विभाग, नई दिल्ली को सूचनार्थ एवं आवश्यक कार्यवाही हेतु।
4. मैसर्स गावर कंस्ट्रक्शन लिमिटेड, डी.डी.स-378, सेक्टर 16-17, हिसार-125005 (हरियाणा) को सूचनार्थ एवं आवश्यक कार्यवाही हेतु।

01/


अधीक्षण अभियंता