

**Details of Traffic Engineering Proposals ( Central Verge/Iron Grills, Closure/opening of cuts, Nose protection, Signages, bollards, jerssy Barriers, U-turn sent to PWD during the year 2018**

Sl. No.	SUBJECT	SENT VIDE NUMBER	DATE	ADDRESSED TO	AGENCY CONCERNED	DISTT	RANGE	REMARKS	Office	PWD
1. /4	Regarding placing crash barriers and central verge grill at Subash Nagar, in Rajouri Garden Area,	No. 279-84/P.Sec/DCP/T-WR	31-Jan-18	The Executive Engineer, PWD, (M-111), R.R. Lines, Ring Road, Dhaula Kuan,	PWD	West Distt.	Western Range	Barriers & Central Verge	South-West Circle	
2. /5	Regarding placing of high height central verge Iron grill at ESI Hospital to Mayapuri Flyover in Rajouri Garden Area.	No. 259-64/P.Sec./DCP/T-WR	31-Jan-18	The Executive Engineer, PWD, Part M-112, Road No. 41, Sainik Vihar,	PWD	West Distt.	Western Range	C.V Grills	South-West Circle	
3. /6	Regarding placing of high height central verge Iron grill at Club Road Punjabi Bagh Ring Road to ESI Hospital Ring Road, Rajouri Garden Are	No. 358-63/P.Sec./DCP/T-WR	01-Feb-18	The Executive Engineer, PWD, Part M-112, Road No. 41, Sainik Vihar,	PWD	West Distt.	Western Range	CV & Iron Grills	South-West Circle	
4. /34	Painting of road markings & installation of signages in the area of Delhi Cantt. Circle	1751-57/SO/DCP/T-SR	12-Apr-18	Exe. Engineer SWR-1, Brar Square, Dhaula Kuan	PWD	South Distt.	Southern Range	road markings signages nose protection device, repair of cv, reflectors,	South-West Circle	

Sl. No.	SUBJECT	SENT VIDE NUMBER	DATE	ADDRESSED TO	AGENCY CONCERNED	DISTT	RANGE	REMARKS	Office	PWD
5. /41	Painting of road markings & installation of signages in the area of R.K. Puram Traffic Circle	1744-50/SO/DCP/T-SR	12-Apr-18	Exe. Engineer SWR -1, Brar Square, Dhaula Kuan	PWD	South Distt.	Southern Range	signages nose protection device, repair of cv, reflectors, rumble strips	South West Circle	
6. /82	Proposal to install high railing (about 8'feet) on central verge in the area of R.K.Puram Circle-  1.Ring Road from South Campus Metro Station till Safdar Jung Bus Stand  2.Swami Venkatesh Marg and Tamil Sangam Marg (Sector-1 to Sector-12 R.K.Puram)  3.Africa Avenue Marg from Hyatt X'ing till Outer Ring	3841-59/SO/DCP/T-SR,	28- Sept.-18	Exe. Engineer, South West, Road-I, PWD, Brar Square, New Delhi	PWD	South	Southern Range	High Railing	South West Circle	

Sl. No.	SUBJECT	SENT VIDE NUMBER	DATE	ADDRESSED TO	AGENCY CONCERNED	DISTT	RANGE	REMARKS	Office	PWD
	Road(Munirka)									
7. /83	Regarding installation of nose protection devices and road safty devices on the exit and entries of flyovers in the area of R.K.Puram Circle-  1.Moti Bagh flyover  2.Hyatt Flyover  3.Raj Nagar flyover	3822-40/SO/ DCP/T-SR,	28- Sept.-18	Exe. Engineer, South West, Road-I, PWD, Brar Square,New Delhi	PWD	South	Southern Range	Nose Protection Device	South-West Circle	
8. /92	Regarding installation of iron grill on central verge of Ram Nath Viz Marg	4506-09/ SO/DCP/T-WR	30-Oct-18	Exe. Engineer, South-West Road- I, PWD (GNCTD), Brar Square, Delhi Cantt.,New Delhi	PWD	West	Western Range	iron grill on central verge	South-West Circle	
9. /99	1.Raise the height of the railing on the Central Verge from IIT to Jia Sarai on the Outer Ring Road to	4644-49/ SO/DCP/T-SR,	11-Dec-18	Exe. Engineer,  M-113(N), South- West,  RMD-1, PWD, GNCTD, Brar	PWD	South	SouthernR ange	Railing on the Central Verge and Shift/remov e or cut the trees	South West Circle	

Sl. No.	SUBJECT	SENT VIDE NUMBER	DATE	ADDRESSED TO	AGENCY CONCERNED	DISTT	RANGE	REMARKS	Office	PWD
	<p>atleast 6 feet</p> <p>2.Shift/remove or cut the trees on the servie road near SDA Markert, Outer Ring Road</p> <p><b>(Regarding speed calming measures on Mehrauli-Mahipalpur Road near Traffic signal of Mehrauli-Mahipalpur Road and Church –only in the subject –speed calming measures not installed)</b></p>			Square, N.D.						