

## Details of Speed Calming Measures Proposals (Pending/Execution) sent to PWD during the year 2019

(upto 30.06.2019)

Sl. No.	SUBJECT	SENT VIDE NUMBER	DATE	ADDRESSED TO	AGENCY CONCERN ED	CONCERNED DISTT	RANGE	REMARKS	Whether Speed Calming Measure has been provided by civic agency or not	Office	PWD
1. /2	Proposal for construction of two speed calming measures at road No. B-3,Sec-15/16 dividing road, Rohini, Delhi.	263-66/TE (D-III)/Traffic	10-Jan-19	Executive Engineer, (North West) Roads-2, Road No. 43, PWD, Sainik Vihar, Near Keshav Mahavidhyalay, Pitampura, New Delhi.	PWD	Outer	Outer Range	SCM	Not Installed	North West Circle	A letter already written to DCP (Traffic) by EE, NWR-2, to resolved by consulting National Human Rights Committee & Senior Citizen Club, Sec-16 because the cut was opened by Delhi Traffic Police at their own
2. /9	Proposal for construction of two speed calming measures in front of school main Gate No. 1 and side Gate No. 2, Prashant Vihar, Rohini, Delhi.	1361-64/TE (D-III)/Traffic	11-Feb-19	Executive Engineer, (North West) Roads-2, Road No. 43, PWD, Sainik Vihar, Near Haryana Maitri Bhawan, New Delhi	PWD	Outer	Outer Range	SCM	Not Installed	North West Circle	<b>Tender recently awarded due to NGT work could not started it may be constructed up to Feb.- Mar.</b>

Sl. No.	SUBJECT	SENT VIDE NUMBER	DATE	ADDRESSED TO	AGENCY CONCERNED	CONCERNED DISTT	RANGE	REMARKS	Whether Speed Calming Measure has been provided by civic agency or not	Office	PWD
3. /18	Regarding construction of speed breaker at Kanhiya Nagar Chowk	1068-71/P.Sec/ DCP/T-OR,	19-Mar-19	Exe. Engineer( C ), North-West, R-1, PWD, Mukarba Chowk, Delhi	PWD	North-West	Outer Range	SCM	Status not available	North-West Circle	SCM installed