Details of Speed Calming Measures Proposals (Pending/Execution) sent to PWD during the year 2018

SI. No.	SUBJECT	SENT VIDE NUMBER	DATE VIDE WHICH SENT	Whether Speed Calming Measure has been provided by civic agency or not Status	Present Status	Office	Status
1./12	Installation for nose protection devices, cat eyes, reflectors, table top, solar studs, fluorescent lamp, rumble strips on cuts (U turns) - on various locations at Rohtak Road,	1301-14/DCP/T-WR	12-Apr-18	Not Installed	Not Installed	West Circle	Rumble strips, cat eyes, & Jerssy barriers has been fixed at different cuts.
2. /40	Construction of speed breakers (Table Top) at Bijwasan - Chhawla Road in front of Gate No. 6, BSF Campus	i i	20-Aug-18	Not Installed	Not Installed	West Circle	Not pertains to this Office
3. /48	Construction of speed calming measures with signages, zebra crossing and installation of "Drive Slow School Ahead" boards in front of schools in the area of Bawana Circle - Naya Bans to Khera Khurd Road (1. Sukriti World School, 2. Sarvodaya Kanya Vidyalaya Khera Khurd, 3. MCD Primary School Khera Khurd)		12-Sep-18	Not Installed	Not Installed	West Circle	Not pertains to this Office
	Road markings/marking yellow strip at the road side stretch as well as installation of speed calming measures on Najafgarh - Nangloi Road (cat eyes, iron grills, signages, rumble strips, table top,		20-Oct-18	Not Installed	Not Installed	West Circle	Work of Iron Grills has been awarded will be completed

SI. No.	SUBJECT	SENT VIDE NUMBER	DATE VIDE WHICH SENT	Whether Speed Calming Measure has been provided by civic agency or not Status		Office	Status
	lane markings etc.)						on 31.03.2020 remaining work like land marking rumbal strip will be 31.03.2020. after completion of carpeting work.
	Regarding installation of speed calming measure "Rumble Strips" at T-Point, Ram Nath Viz Marg, BSNL Colony near Arya Mahila Ashram		22- Nov-18	Not Installed	Not Installed		Not pertains to this Office
·	Regarding installation of speed breakers on arterial roads of Rohtak Road from Peeragarhi to Tikri Border – 1.Tikri PVC More 2.Ghevr More	4668-71/ SO/DCP/T-WR	30- Nov-18	Not Installed	Not Installed	West Circle	Rumle strips, cat eyes, reflectors has been fixed at all cuts between Mundka to Tikri (both

SI. No.	SUBJECT	SENT VIDE NUMBER	DATE VIDE	Whether Speed Calming Measure has been provided by civic agency or not Status	Office	Status
	3.Neelwal More 4.Rani Khera More					sides) as Suggested by Traffic Police.
	5.Jawalapuri More					