

Details of Traffic Engineering Proposals (Central Verge/Iron Grills, Closure/opening of cuts, Nose protection, Signages, bollards, jerssy Barriers, U-turn sent to PWD during the year 2018

Sl. No.	SUBJECT	SENT VIDE NUMBER	DATE	ADDRESSED TO	AGENCY CONCERNED	DISTT	RANGE	REMARKS	Office	PWD
1. /4	Regarding placing crash barriers and central verge grill at Subash Nagar, in Rajouri Garden Area,	No. 279-84/P.Sec/DCP/T-WR	31-Jan-18	The Executive Engineer, PWD, (M-111), R.R. Lines, Ring Road, Dhaula Kuan,	PWD	West Distt.	Western Range	Barriers & Central Verge	South-West Circle	
2. /5	Regarding placing of high height central verge Iron grill at ESI Hospital to Mayapuri Flyover in Rajouri Garden Area.	No. 259-64/P.Sec./DCP/T-WR	31-Jan-18	The Executive Engineer, PWD, Part M-112, Road No. 41, Sainik Vihar,	PWD	West Distt.	Western Range	C.V Grills	South-West Circle	
3. /6	Regarding placing of high height central verge Iron grill at Club Road Punjabi Bagh Ring Road to ESI Hospital Ring Road, Rajouri Garden Are	No. 358-63/P.Sec./DCP/T-WR	01-Feb-18	The Executive Engineer, PWD, Part M-112, Road No. 41, Sainik Vihar,	PWD	West Distt.	Western Range	CV & Iron Grills	South-West Circle	
4. /34	Painting of road markings & installation of signages in the area of Delhi Cantt. Circle	1751-57/SO/DCP/T-SR	12-Apr-18	Exe. Engineer SWR-1, Brar Square, Dhaula Kuan	PWD	South Distt.	Southern Range	road markings signages nose protection device, repair of cv, reflectors,	South-West Circle	

SI. No.	SUBJECT	SENT VIDE NUMBER	DATE	ADDRESSED TO	AGENCY CONCERNED	DISTT	RANGE	REMARKS	Office	PWD
5. /41	Painting of road markings & installation of signages in the area of R.K. Puram Traffic Circle	1744-50/SO/DCP/T-SR	12-Apr-18	Exe. Engineer SWR -1, Brar Square, Dhaula Kuan	PWD	South Distt.	Southern Range	signages nose protection device, repair of cv, reflectors, rumble strips	South West Circle	
6. /82	Proposal to install high railing (about 8'feet) on central verge in the area of R.K.Puram Circle- 1.Ring Road from South Campus Metro Station till Safdar Jung Bus Stand 2.Swami Venkatesh Marg and Tamil Sangam Marg (Sector-1 to Sector-12 R.K.Puram) 3.Africa Avenue Marg from Hyatt X'ing till Outer Ring	3841-59/SO/DCP/T-SR,	28- Sept.-18	Exe. Engineer, South West, Road-I, PWD, Brar Square,New Delhi	PWD	South	Southern Range	High Railing	South West Circle	

Sl. No.	SUBJECT	SENT VIDE NUMBER	DATE	ADDRESSED TO	AGENCY CONCERNED	DISTT	RANGE	REMARKS	Office	PWD
	Road(Munirka)									
7. /83	Regarding installation of nose protection devices and road safty devices on the exit and entries of flyovers in the area of R.K.Puram Circle- 1.Moti Bagh flyover 2.Hyatt Flyover 3.Raj Nagar flyover	3822-40/SO/ DCP/T-SR,	28- Sept.-18	Exe. Engineer, South West, Road-I, PWD, Brar Square,New Delhi	PWD	South	Southern Range	Nose Protection Device	South-West Circle	
8. /92	Regarding installation of iron grill on central verge of Ram Nath Viz Marg	4506-09/ SO/DCP/T-WR	30-Oct-18	Exe. Engineer, South-West Road- I, PWD (GNCTD), Brar Square, Delhi Cantt.,New Delhi	PWD	West	Western Range	iron grill on central verge	South-West Circle	
9. /99	1.Raise the height of the railing on the Central Verge from IIT to Jia Sarai on the Outer Ring Road to atleast 6 feet	4644-49/ SO/DCP/T-SR,	11-Dec-18	Exe. Engineer, M-113(N), South- West, RMD-1, PWD, GNCTD, Brar	PWD	South	SouthernR ange	Railing on the Central Verge and Shift/remov e or cut the trees	South West Circle	

Sl. No.	SUBJECT	SENT VIDE NUMBER	DATE	ADDRESSED TO	AGENCY CONCERNED	DISTT	RANGE	REMARKS	Office	PWD
	<p>2.Shift/remove or cut the trees on the servie road near SDA Markert, Outer Ring Road</p> <p>(Regarding speed calming measures on Mehrauli-Mahipalpur Road near Traffic signal of Mehrauli-Mahipalpur Road and Church –only in the subject –speed calming measures not installed)</p>			Square, N.D.						