

Details of Speed Calming Measures Proposals (Pending/Execution) sent to PWD during the year 2018

Sl. No.	SUBJECT	SENT VIDE NUMBER	DATE VIDE WHICH SENT	Whether Speed Calming Measure has been provided by civic agency or not Status	Present Status	Office	Status
1. /2	Regarding installation of speed calming device at main gate of Maharshi Dayanand Gosamwardhhran Kendra, near Central Ware, Gazipur	No. 45-49/SO/DCP/T-ER	03-Jan-18	Not Installed	Not Installed	East Circle	SCM Not pertain to Div. M-212. It pertain to EDMC
2. /7	Installation of speed calming device at main gate of Maharishi Dayanand Gosamwardhhran Kendra, near Central Ware House, Gazipur	No. 465-68/SO/DCP/T-ER	07-Feb-18	Not Installed	Not Installed	East Circle	SCM Not pertain to Div. M-212. It pertain to EDMC
3. /8	Regarding installation of Speed Calming Device at main gate of Mahrishi Dayanand Gosamwardhhran Kendra, Near Central Ware House, Gazipur	No. 621-624/SO/DCP/T-ER	05-Mar-18	Not Installed	Not Installed	East Circle	SCM Not pertain to Div. M-212. It pertain to EDMC
4. /17	Installation of speed calming device (rumble strip) at Service lane Vikas Marg between F-26 to F-11, Preet Vihar	1259-62/SO/DCP/T-ER	17-Apr-18	Not Installed	Not Installed	East Circle	SCM has been installed and completed
5. /26	Installation of speed calming device/speed breaker as per IRC guidelines at F-Block near	1810-13/SO/DCP/T-ER	02-Jul-18	Not Installed	Not Installed	East Circle	SCM Installed

Sl. No.	SUBJECT	SENT VIDE NUMBER	DATE VIDE WHICH SENT	Whether Speed Calming Measure has been provided by civic agency or not Status	Present Status	Office	Status
	JhankarBanquet, Jain Temple Preet Vihar						
6. /47	Installation of speed calming device/speed breakers as per IRC guidelines at underpass School Block Shakarpur on both carriageways in front of Jitender Band & BS Auto Deal, D-371	2475-78/SO/DCP/T-ER	07-Sep-18	Not Installed	Not Installed	East Circle	Installed
7. /51	To provide more street lighting near Geeta Colony flyover & speed calming measures etc. at Raja Ram Kohli Marg (Shantivan side) [SCM at the loops of Raja Ram Kohli Marg]	2845-50/P. Sec./DCP/T-CR	15-Oct-18	Not Installed	Not Installed	East Circle	SCM Installed and Street light pertain to Elect. Div
8. /55	Developing of speed calmers on Noida Link road under flyover opposite Star City Mall	2843-62/SO- DCP/T-ER	26-Oct-18	Not Installed	Not Installed	East circle	SCM Installed
9. /56	Developing of speed calmers in front of Paradise Apartment both carriage way Narwana Road	2843-62/SO- DCP/T-ER	26-Oct-18	Not Installed	Not Installed	East Circle	SCM Installed
10. /60	Regarding request for installing of speed calming device- 1.Madhu Vihar Red Light towards Karkari more slip down road in front of SBI Bank 2.Karkarimore towards Madhu Vihar	3284-87/ SO/DCP/T-ER	20- Nov-18	Not Installed	Not Installed	East Circle & Shahdara Circle	5. SCM Installed and S.No. 1 to 4 & 6 Pertain to Div. M-211

Sl. No.	SUBJECT	SENT VIDE NUMBER	DATE VIDE WHICH SENT	Whether Speed Calming Measure has been provided by civic agency or not Status	Present Status	Office	Status
	<p>Red light slip down upwards before merging point in front of Electricity Poll No. 11</p> <p>3.Karkari More Flyover top downwards to JagatpuriNala before traffic merging point</p> <p>4. Speed calmer before near Hasanpur Village Bus Stop carriageway, Hasanpur Red Light towards Road No. 56</p> <p>5.In front of Paradise Apartment, Narwana Road</p> <p>6.On Road No. 57 A before entering to slip down Road NH-9, Hasanpur Red Light towards slip down NH-9 Road</p>						
11. /64	Regarding request for installing of rumble strips and speed calming measures on slip road connecting NH-09 to Noida Link Road near Akshardham Setu in the area of Kalyanpuri Circle	3667-70/ SO/DCP/T-ER	10-Dec-18	Not Installed	Not Installed	East Circle	SCM Installed