



दिल्ली सरकार प्रमुख अभियंता, लो०नि०वि०,

12वां तल, बहु-मंजिला भवन, इंद्रप्रस्थ संपदा, नई दिल्लीः 110002 🕾 23490439, 23490260, 23724560 फेक्स 23319021





सं0ः प्रमुख अभि/अनु0/लोनिवि/Misc./2025/1438



दिनांक:. /8 .03.2025

कार्यालय ज्ञापन

It has been noticed that field formation i.e. JEs/AEs and EEs are not doing proper periodic inspection of their jurisdiction of roads and they are not even aware of pot holes, patches, broken foot path, Kerb stone, poor condition of central verge, encroachments and dumped Malba etc. in their jurisdiction. They are also not using PWD e-monitoring application. This is very serious issue and attention of senior officers i.e. SEs and CEs is warranted.

In view of above it is therefore directed that all field formations will upload their daily inspection reports in PWD E-Monitoring application and senior officers will login and review the compliance at least once in a week.

This issues with the approval of E-in-C, PWD, GNCTD.

उपनिदेशक (अनुवीक्षण)

प्रतिलिपि:

- 1. प्रधान मुख्य अभियंता(अनु. एंव सेतुं), लो.नि.वि, दिल्ली सरकार, नई दिल्ली।
- 2. प्रधान मुख्य अभियंता(परियोजनाएं), लो.नि.वि, दिल्ली सरकार, नई दिल्ली।
- 3. सभी मुख्य अभियंता, लो.नि.वि, दिल्ली सरकार, नई दिल्ली।
- 4. सभी अधीक्षण अभियंता, लो.नि.वि, दिल्ली सरकार, नई दिल्ली।
- 5. सभी कार्यपालक अभियंता, लो.नि.वि, दिल्ली सरकार, नई दिल्ली।
- सभी सहा० अभियंता, एवं कनिष्ठ अभियंता, लो.नि.वि
- PWD वेबसाइड पर अपलोड हेत्।

PWD वेबसाइड के द्वारा कार्यवाही हेतु प्रेषित।

उपनिदेशक (अनुवीक्षण)