

Inspection Note

Sub: - Inspection regarding desilting of big pipe drain and natural drain near culvert at Westend Marg and Saket Metro Station on MB Road.

A site Inspection held on 21.04.2025 to resolve the issue of water logging/flooding near Saket Metro Station & Westend Marg by **Sh. Vivekanand Vivek, ADG (Project)** and following officials were present-

1. A. K. Jalan, SE, South (M)
2. L.K.Pal, AE, South Road-1/SR-11
3. Rana Abhishek, JE, South Road-1/SR-11

During the inspection following points were discussed: -

1. To check the details of natural drain coming from forest area in upstream and submit the detail of findings.
2. At starting point where the MS grating is fixed silt is to be cleaned between grating and culvert mouth along with the inside cleaning of culvert.
3. To check the cross-sectional area of culvert crossing on PWD Road and the RCC pipe in downstream passing through DDA land and metro parking area.
4. The pipe drain in downstream is passing through DDA land area and DMRC parking area and finally falls at junctions point under FOB at MB Road. Manholes situated in DDA land and Saket Metro parking area were opened and checked and it is observed that water is running slowly in pipes due to probable obstruction and hence need proper cleaning. Instructions given to write the letter to DMRC for proper cleaning of pipes before monsoon to avoid water logging.
5. Many paver blocks near Saket FOB found settled for which instructions given for repair of the same at earliest.
6. Saket FOB CISF side one lift is found non operational for which instructions has been given to Sh. Rohit Kumar, EE (E) South to get repaired the lift at earliest.
7. Various pamphlets found pasted on FOB pillars near lift Saudulajab village side instructed to remove the pamphlets immediately.
8. Auto parking observed near the Saket Metro Station Gate No. 2 causing hindrance at road, hence instructed to communicate with the traffic department to clear the same.
9. Bell mouth under the FOB found not cleaned need to clean immediately and check the all bell mouths on roads.
10. Broken slabs in DDA land area found instruction given to change this one and check any other on PWD road.

11. Drain portion at Westend Marg from big drain to M.B. Road found not cleaned hence need cleaning urgently.
12. Instruction given to cover the open channel near the Saket Metro station gate no. 2 with perforated RCC drain cover.

ADG (Projects)
PWD, New Delhi

Copy to:

1. -----
2. -----

ADG (Projects)