

कार्यालय अधीक्षण अभियंता
गुणवत्ता आश्वासन इकाई,
लो.नि.वि. रा.रा.क्षे.दिल्ली,
11वां तल, लोक निर्माण विभाग मुख्यालय,
इंद्रप्रस्थ एस्टेट, नई दिल्ली-110002
दूरभाष: 23317790, 23318921

O/o THE SUPERINTENDING ENGINEER
QUALITY ASSURANCE UNIT, PWD NCT Delhi.
11th FLOOR, P.W.D. HEADQUARTERS, I.P. ESTATE,
NEW DELHI- 110002
PHONE : 23317790, 23318921
Email: sepwdldelhiqau@gmail.com

सं०: 23(1)/अधी०अभि०/गु.आ.ई./लो.नि.वि./237 (14)

दिनांक: 05/06/2025

Office Memorandum

Sub.: Third Party Audit of work of Desilting of PWD Drains.

The third party audit of desilting work of PWD drains is required to taken up on urgent basis.

The competent authority has directed to take up third party audit of the work of Desilting of PWD Drains by the concerned Chief Engineers immediately.

This issues with the approval of competent authority.

Superintending Engineer (QAU)
QAU, PWD Delhi.

Copy To:

1. The Pr. Chief Engineer (Project), PWD, (GNCTD), 9th Floor, MSO Building, I. P. Estate, New Delhi- 110002.
2. The Pr. Chief Engineer (Maintenance), PWD, (GNCTD), 12th Floor, MSO Building, I. P. Estate, New Delhi- 110002.
3. The Chief Engineer (East), PWD, (GNCTD), 3rd Floor, MSO Building, I. P. Estate, New Delhi- 110002.
4. The Chief Engineer (North), PWD, (GNCTD), 5th Floor, MSO Building, I. P. Estate, New Delhi- 110002.
5. The Chief Engineer (South), PWD, (GNCTD), 7th Floor, MSO Building, I. P. Estate, New Delhi- 110002.
- ✓ 6. All SE's & EE's of Road Divisions through PWD Website.

Superintending Engineer (QAU)