

राष्ट्रीय राजधानी क्षेत्र दिल्ली सरकार
GOVT. OF NATIONAL CAPITAL TERRITORY OF DELHI

कार्यालय अधीक्षण अभियन्ता सी०बी०एम०सी० एम-22, लोक निर्माण विभाग, द्वितीय तल, दिल्ली सचिवालय, नई दिल्ली-110002 फोन नं० 23392194	Office of the Superintending Engineer CBM Circle M-22, PWD, Level-2, Delhi Sachivalaya, New Delhi-2 Fax no. 23392191
--	--

सं० 23(क्यू.सी./लो०नि०वि०/सि०भ०अनु०परि०एम-22/ 658 दिनांक 18/3/14

सेवा में,

मुख्य अभियंता,
भवन अनुरक्षण अंचल एम - 2,
लो.नि.वि., एम.एस.ओ. भवन,
तृतीय तल, नई दिल्ली।

विषय: अधीक्षण अभियंता, परिमंडल एम-22 द्वारा किये गए निरीक्षणों का ब्यौरा।

संदर्भ: सचिव (लो.नि.वि.) का पत्र सं. PS PWD/119-128 दिनांक 04.03.2014

क्र. सं.	दिनांक	विवरण	टिप्पणी
1	10/03/14	Inspection of Sanskar Ashram works.	The directions were given to field staff for (a) Use of hollow polycarbonate sheet for temporary roof. (b) Use better quality marble. (c) Improvement in workmanship etc.
2	11/03/14	Inspection of 18 nos. SPS at Mandoli Ext. & 13 nos. SPS at New Seelampur	The directions were given to field staff for (a) Progress of works should be monitored. (b) Single piece of kota stone should be used for staircase steps. (c) Material as per approved list should be allowed. (d) Sand papering of wall should be done to have a proper surface.
3	12/03/14	Inspection of double storyed Women Wing at I.T.I. Nand Nagari, Delhi	The directions were given to field staff for (a) To ensure proper mix & mixing of water proofing compound for brick koba treatment of roof. (b) Rain water spout should be fix before roof treatment. (c) Seeing the requirement of building for election the progress should be monitored. (d) C.C. pathway should also be made for proper approach of the building.
4	13/03/14	Meeting with Secretary, GAD for the maintenance of Delhi Sachivalaya Building	Secretary, GAD has desired that as per pattern of CPWD, the case for approval of declaring Delhi Sachivalaya. Vidhan Sabha & L.G. House as V.I.P. Buildings should be made.
5	14/03/14	Inspection of 40 Nos. SPS type additional Class Rooms at Govt. S.K.V. Old Seemapuri, Delhi	The directions were given to field staff for (a) Progress of works should be monitored. (b) Single piece of kota stone should be used for staircase steps. (c) Material as per approved list should be allowed. (d) Sand finishing of wall should be done to have a proper surface.

xlj
18/3/14
अधीक्षण अभियंता

सि.भ.अनु.परि.एम-22, लो.नि.वि.,
दिल्ली सचिवालय, नई दिल्ली

प्रतिलिपि:-

- कार्यपालक अभियंता, लो.नि.वि. मं. एम-221, दिल्ली सचिवालय, नई दिल्ली।
- कार्यपालक अभियंता, लो.नि.वि. मं. एम - 222, मानसरोवर पार्क, शाहदरा, दिल्ली।

(इस कार्यालय का पत्र सं. 23(विविध)/Vol-II/सि.भ.अनु.परि. एम-22/575 दिनांक 05.03.14 के अनुक्रम में रिपोर्ट इस कार्यालय को प्रेषित करें।)

xlj
18/3/14
अधीक्षण अभियंता