राष्ट्रीय राजधानी क्षेत्र दिल्ली सरकार GOVT. OF NATIONAL CAPITAL TERRITORY OF DELHI

4011.01.1011	
कार्यालय अधीक्षण अभियंता	O/o Superintending Engineer
	CBM Circle M-22,
सी.बी.एम.सी. एम - 22,	Public Works Department, Level-2,
लोक निर्माण विभाग, द्वितीय तल,	Delhi Sachivalaya, New Delhi-2
दिल्ली सचिवालय, नई दिल्ली - 110002	
फोन नं. 23392194	Fax no. 23392191
· • • • • • • • • • • • • • • • • • • •	087 दिनांक 615119

सं. 23(क्यू.सी.)/लो.नि.वि./सि.भ.अन्.परि.एम-22/

90t

दिनाक 6/2/17

सेवा में,

म्ख्य अभियंता, भवन अन्रक्षण अंचल एम - 2, लो.नि.वि., एम.एस.ओ. भवन, ततीय तल, नई दिल्ली।

अधीक्षण अभियंता, परिमंडल एम-22 द्वारा किये गए निरीक्षणों का ब्यौरा। विषयः

सचिव (लो.नि.वि.) का पत्र सं. PS PWD/119-128 दिनांक 04.03.2014 संदर्भः

उपरोक्त विषय एवं संदर्भ में, अधीक्षण अभियंता, परिमंडल एम-22 द्वारा किये गये निरीक्षणों का ब्यौरा निम्नवत् है।

दिनांकः 28/04/2014

The work of "20 Nos. SPS Type A.C.R. at GGSSS Saboli, Delhi" was inspected. The directions were given to field staff for

(a) The progress of work should be expedited.

(b) The proper hacking should be done on RCC bands.

(c) Primer coat should be done on the steel before fixing.

दिनांकः 29/04/2014 एवं 01/05/2014

The joint Sachivalaya done. inspection of Delhi was GAD, Civil and Electrical officers is being carried out on regular basis. The directions were given to field staff for

(a) Inviting of tenders of A/R & M/O works of Delhi Sachivalaya.

(b) The work pertaining to water proofing should be taken up on urgent basis.

दिनांकः 30/04/2014

The work of "40 Nos. SPS type A.C.R. at Govt. S.K.V. Old Seemapuri, Delhi" was inspected. The directions were given to field staff for

(a) The progress of work should be expedited.

(b) The proper hacking should be done on RCC bands.

दिनांकः 02/05/2014

The work of "13 Nos. SPS Type A.C.R. at New Seelampur, Delhi" was inspected. The directions were given to field staff for

(a) Roof should be finished with multi surface paint (as per DSR Item No. 13.8) instead of distempering on plaster roof surface/synthetic enamel paint on angles. However R.S. joist should be painted with synthetic enamel paint as per agreement.

की श्रीत अधीक्षण अभियंता सि.भ.अनु.परि.एम-22, लो.नि.वि., दिल्ली सचिवालय, नई दिल्ली

प्रतिलिपिः-

कार्यपालक अभियंता, लो.नि.वि. मं. एम-221, दिल्ली सचिवालय, नई दिल्ली को सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित।

2. कार्यपालक अभियंता, लो.नि.वि. मं. एम-222, मानसरोवर पार्क, शाहदरा, दिल्ली को सूचनार्थ एवं आवश्यक न्ताः स्ति अधीक्षण अभियंता कार्यवाही हेत् प्रेषित।