CROWN PLAZA TO ONWARD ON ROAD NO.13: C)

- Kerb channel not cleared properly i)
- Earth dumping, steel girders & construction machinery seen at carriageway before ii) underpass. Contact to DDA for removal of the same.
- Malba after drain cleaning dumped on drain side it is to be removed immediately. iii)
- Unauthorized encroachment seen LHS of carriageway to be removed immediately. iv)
- Truck, trailers, cranes seen standing in carriageway. Contact to concerned deptt. for V) removal.

D) GENERAL:

- Both the roads are badly infested with encroachments and unauthorized parking, i) vending etc. Matter may be taken up with Police Authorities & these roads may be pursued to be included in list of corridor encroachment removal drive.
- On both roads, central verge is filthy & full of dumping. Matter may be taken up with ii) DD (H), PWD and Deptt. of Environment, GNCTD for proper upkeep & beautification.

Superintending Engineer

8 C M-44

Copy to:

1- The Chief Engineer. MZ M-4, PWD, New Delhi for information please

2- EE M-441 PWD for information & necessary compliance & for submitting ATR within a week's time.

3- Guard File.

Superintending Engineer