

Office of the Engineer-in-Chief
Public Works Department
P.W.D., Govt. of NCT of Delhi.
12th Floor, M S O Building, I P Estate, New Delhi 110 002
Phone 011 2349 0260/ 011 23319021

Sub: Inspection diary of Shri Dinesh Kumar, Engineer-in-Chief, PWD for the week from 14th to 18th of July 2014.

Ref: No.PS/PWD/119-128 dated 4.3.2014 from PWD Sectt.

14/7/2014 : Inspection of Aurbindo Marg, South Extension and Barapullah.

An inspection was carried out for Gautam Nagar drain, Aurbindo Marg drain and Barapullah nallah where Project Manager, F-12, E.E, M-113 and E.E, M-412 along with their staff were present. Construction of culvert across Aurbindo Marg has almost been completed. It has been directed that water may be opened in the newly constructed drain if problem occur during rain; otherwise traffic may be opened after completion of curing period of the culvert and shuttering may be removed from the culvert within a week. Desilting of Gautam Nagar culvert under Ring Road was being done by E.E, M- 412 which was satisfactory. Detailed inspection was carried out for desilting of Barapullah nallah and suitable directions issued to Project Manager, F-12 to expedite desilting work.

15/7/2014 : Meeting of Hon'ble L.G.

There was a meeting of Hon'ble L.G at 10.30 a.m regarding desilting of drains etc; hence no inspection could be done.

16/7/2014 : Inspection of Delhi High Court.

Inspection of Delhi High Court was conducted where C.E, M-4, S.E, M-43, S.E(E) M-45 and their staff were present. Details of the projects for construction of new blocks were reviewed. The progress still needs expediting for which detailed inspection note is to be issued by C.E, M-4.

17/7/2014 : Meeting of Hon'ble L.G.

There was a meeting of Hon'ble L.G at 11.15 a.m regarding re-development of East Kidwai Nagar; hence no inspection could be done.

18/7/2014 : Inspection of Ring Road from Moti Bagh to ITO.

There was heavy rain fall on 17/7/2014; hence a general round was taken along Ring Road from Moti Bagh to ITO and some other roads. Suitable directions were

issued to concerned S.E and C.E to clear minor water logging noticed on sid channels.

Submitted for information of Secretary, PWD/Chief Secretary.

de
(Dinesh Kumar
Engineer-in-Chief, PWI

The Secretary, PWD
S.O to Chief Secretary

No. E-in-C/PWD/M/IR/ 3037(E) dated : 22.7.2014

Copy to :

All Chief Engineers of PWD.

de
Engineer-in-Chief