Office of the Engineer-in-Chief Public Works Department P.W.D., Govt. of NCT of Delhi. 12th Floor, M S O Building, I P Estate, New Delhi 110 002 Phone 011 2349 0260/ 011 23319021

Sub: Inspection diary of Shri Dinesh Kumar, Engineer-in-Chief, PWD for the week from 30th June to 4th of July 2014.

Ref: No.PS/PWD/119-128 dated 4.3.2014 from PWD Sectt.

30/6/2014: Visit of Bhairon Road, NH-24 etc.

A round was taken from Bhairon Road to NH-24 and back to ITO. At lot of places, bell mouths and side channel was found chocked and at some places water was stagnated near bell mouths. Concerned S.Es were directed for got cleared the same urgently. A general instruction was also issued to all E.Es/S.Es dealing with roads, to ensure cleaning of bell mouths and channels at the earliest.

1/7/2014: Inspection of Ring Road from Moti Bagh to ITO.

Ring Road from Moti Bagh to ITO was inspected for checking the clearance of bell mouths and side channels. It was noticed that at some places, workers were deployed for cleaning of bell mouths and channels but the same is to be continued for all the rainy season as cleaning of bell mouths and channels is a regular affair. Concerned E.E/S.E has been directed accordingly. Near T-point of NH-24, Ring Road, water stagnation on one of the edge was found for which E.E and S.E has been directed to make a permanent solution to this water stagnation. Near Bhairon Road – Ring Road T-point, the Islands needs greening. Dy. Director (Hort) has to take action immediately. Restoration of greening from ITO to Nizamuddin is also to be taken up immediately. Director (Hort) and Dy. Director (Hort) have to take necessary action accordingly.

2/7/2014: Function at CPWD Training Institute, Ghaziabad.

There was an inauguration of foundation training of AEEs 2012 batch at CPWD Training Institute, Ghaziabad which was attended by E-in-C; hence no inspection could be done.

3/7/2014: Inspection of Barapullah Phase-II.

Inspection of Barapullah Phase-II was conducted where C.E, F-1 and his staff were present. The stretch of Barapullah from INA to Yamuna River was inspected. Suitable directions were issued for cleaning of water way wherever construction has been undertaken by PWD.

The progress of construction of Elevated Road was also reviewed. It was directed that all pending drawings should be got cleared at the earliest and identify the

location where work can be done during rainy season and ensure that speed of the work is maintained.

4/7/2014: Meeting at CPWD, Nirman Bhawan.

There was meeting at D.G, CPWD's office at 10.00 a.m regarding selection best performer for award during celebration of CPWD Day; hence no inspection of be done.

Submitted for information of Secretary, PWD/Chief Secretary.

(Dinesh/Kur Engineer-in-Chief, F

The Secretary, PWD
S.O to Chief Secretary

No. E-in-C/PWD/M/IR/ 2800 (Edated: 8 .7.2014

Copy to:

All Chief Engineers of PWD.

Engineer-in-

de