

कार्यालय मुख्य अभियंता

लोक निर्माण विभाग, अनुरक्षण अंचल- एम 4

राष्ट्रीय राजधानी क्षेत्र (दिल्ली सरकार)

9वां तल, एम.एस.ओ. भवन,

नई दिल्ली- 110002

दूरभाष : 23319795/ फ़ैक्स: 23317728

न०. 23(25) /CEM-4/PWD/GNCTD/ 2-98



O/o THE CHIEF ENGINEER

PWD MAINTENANCE ZONE -M4

GNCTD, 9TH FLOOR, M.S.O. BUILDING

I.P. ESTATE, NEW DELHI- 110002

Phone: 23319795 Fax: 23317728

Email: cepwddelhimzm4@gmail.com

दिनांक: -25/03/2015

Inspection Note

The Chief Engineer, PWD, Maintenance Zone M-4 has inspected various roads under Circle M-41 on 25.03.2015 alongwith Shri G.P. Bansal, Superintending Engineer, M-41.

Following observations have been made:-

1. Captain Gaur Marg:

- (i) Allegater cracks and potholes have been noticed on the Captain Gaur Marg.
- (ii) At the junction of Captain Gaur Marg and Ring Road, nosing and Central Verge found damaged.
- (iii) Kerbstones found missing and dislocated from its place.
- (iv) Earth spill over on the road surface from the central verge at some places.

2. S.A. Marg.

- (i) At the junction of S.A. Marg and Outer Ring Road potholes and tracks have been noticed on the slip road.
- (ii) At the junction of Ravi Das Marg and S.A. Road cracks and potholes have been observed.
- (iii) Some kerb stones were also found dislocated.

3. Mathura Road,

- (i) Potholes and cracks on the road surface noticed at a no. of places.
- (ii) Some kerb stones found missing from footpath.
- (iii) Paver blocks found missing from footpath at 2-3 places.
- (iv) Kerbstones found dislocated from the Central Verge at some places.
- (v) Condition at junction of Nizamuddin and Mathura Road is not satisfactory.

(जयेश कुमार)

मुख्य अभियंता

अनुरक्षण अंचल- एम 4

प्रतिलिपि:-

- 1 सचिव, लो०नि०वि०, 5वां तल, बी विंग, दिल्ली सचिवालय, नई दिल्ली 110002 को सूचनार्थ प्रेषित।
- 2 प्रमुख अभियन्ता लो०नि०वि०, 12वां तल, एम० एस० ओ० भवन, इन्द्रप्रस्थ सम्पदा, नई दिल्ली 110002 को सूचनार्थ प्रेषित।

प्रतिलिपि सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित:-

- 1 श्री जी. पी. बंसल, अधीक्षण अभियन्ता, अनुरक्षण परिमण्डल एम-41, भैरो रोड, टी-जंक्शन, नियर प्रगति पावर स्टेशन, नई दिल्ली।
- 2 श्री बिनोद कुमार, कार्यपालक अभियन्ता, रोड्स अनुरक्षण मंडल एम 411 लो० नि० वि०, जे.बी. टीटो मार्ग, एन्द्रयुज गंज, नई दिल्ली 110049।

3 गार्ड फाईल।

मुख्य अभियन्ता