

अधीक्षण अभियंता

परिमंडल एम-41

लोक निर्माण विभाग, दिल्ली सरकार
भैरों रोड, टी-जंक्शन, नियर प्रगति पावर स्टे०

नई दिल्ली 110002

फोन व फ़ैक्स न. 23379694 / 23379693



आपके सपनों को साकार करते हुए
आपके लिए दिल्ली का निर्माण करते हुए

Superintending Engineer

Circle : M-41

Public Works Department

Govt. of NCT of Delhi

Bhairon Road, T-Junction

Near Pragati Power Station, N.D.-02

Phone & Fax No. 23379694/23379693

No. 23(15)/M-412/CRMC/M-41/2015-16/1975 Dated: 11/6/15

INSPECTION NOTE

Sub: Inspection of Superintending Engineer, M-41, PWD of Ring Road & NH-2 on 06-05-15.

The undersigned inspected the Ring Road & NH-2 along with Sh. C. S. Azad, Executive Engineer, M-412, PWD and concerned Assistant Engineer in charge on 06-05-15.

1. Ring Road :-

- (i) Sh. Chander Shekhar Azad, EE, M-412, PWD.
- (ii) Sh. G. A. Khan, AE, M-4123, PWD.


- The kerb channel needs cleaning regularly. It seems there is some laxity in cleaning of kerb channel and bell mouth. The bell mouths at various places are not maintained properly.
- The service road near Andrews Ganj upto August Kranti Marg point is not in good condition.
- During the inspection, it was found that alligator cracks are appearing on the road surface. The Executive Engineer intimated that necessary action for filling of the cracks is being taken.
- The maintenance van is required to be activated efficiently as at some places the repair of nosing / footpath to be handled by maintenance van is not being done.

2. NH-2 :-

- (i) Sh. Chander Shekhar Azad, EE, M-412, PWD.
- (ii) Sh. A. K. Dixit, AE, M-4122, PWD.


- The maintenance of this stretch (Ashram chowk to Mata Mandir Marg) of road is not satisfactory inspite of the directions given by the undersigned many times, though replacement of interlocking paver blocks was going on near Friends Colony.
- There are number of vulnerable points on NH-2 & at Ashram Chowk related to water logging, EE, AE & JE in charge shall inspect this vulnerable points and ensure there is no hindrance to flow of water during the monsoon.

The ATR may be submitted within 7 days of issue of this inspection note.


/c (जी पी बंसल)
अधीक्षण अभियंता

प्रतिलिपि :-

- 1 मुख्य अभियंता, अनु०अंचल, एम-4, लो० नि० वि०, 9वां तल, एम.एस.ओ.भवन, नई दिल्ली-110002।
- 2 श्री चन्द्र शेखर आजाद, कार्यपालक अभियन्ता, सिविल रोड अनुरक्षण मंडल, एम - 412, लो०नि०वि०, दिल्ली।
- 3 Guard File.


/c अधीक्षण अभियंता