# राष्ट्रीय राजधानी क्षेत्र दिल्ली सरकार लोक निर्माण विभाग



कार्यालय मुख्य अभियंता उत्तरी अंचल (एम.) लोक निर्माण विभाग, दिल्ली सरकार, पाँचवा तल, एम.एस.ओ. भवन, इन्द्रप्रस्थ एस्टेट, नई दिल्ली 110002

### GOVT. OF NCT OF DELHI PUBLIC WORKS DEPARTMENT

OFFICE OF CHIEF ENGINEER
North Zone (M), PWD,
GNCTD, 5th Floor, M.S.O. Building,
I.P. Estate, New Delhi -110002.



Ph: 011-23325033, 23319952 Fax: 011-23356195

No. 23/AE(P)/M-13/M-3/Insp. Note/ 49/- 5

e-mail:cepwddelhimzm3@gmail.com

Dated:- 03/06/2016

## Inspection Report of Chief Engineer (North), PWD on 01-06-2016

The various roads and progress of desilting works on various drains Hari Nagar Consituency were inspected by the undersigned alongwith Sh. A. K. Sahana, Executive Engineers (West) Road-1, concerned Assistant Engineer, A.D. (Hort.) and others.

- It could be seen during inspection that in general the maintenance of the roads is in pathetic conditions inspite of the facts that Roads / Horticulture division are incurring huge expenditure in maintenance of roads.
- Even after the recent tragic i.e. fatal accident of child and cautionary advice and strict instructions were issued by Pr. CE (Maint.) as well as by undersigned many of the drain covers are open. There are large gaps in between concrete slabs placed on the drain. Situation is alarming because these drains are also designed as footpath on top.
- Not a single stretch of the road is in good condition.
- 4. Even small things which required little expenditure are not being attended. There are lots of bald surface with malba / garbage are littering on these spaces, which are supposed to be maintained green.
- 5. Some of the defects notices during inspection are listed on below. This is just to give the idea what our Engineers and maintenance staff are performing even after having a large contingent of engineers, huge team of maintenance staff / labour and number of maintenance vans.

### Janak Setu

- At starting point (Cantonment Side) potholes should be repaired.
- Cement Concrete around electric pole in central verge to be done.
- Loose malba lying on central verge to be removed.
- One electrical lamp post is missing.
- Some of the street lamps are hanging.

#### Lajwanti Flyover

- At starting point, there is settlement of road.
- Loose stones/ Malba lying on centre verge.

#### Jail Road (Saheed Bhagat Singh Marg)

- In front of Jail Gate, Malba found lying.
- Manhole cover to be placed properly.
- Railing in central verge tilted in various locations.
- Gap filling in hedges/shrubs in of central verge required.
- In central verge, plants are drying for want of water. A.D. (Hort.) should check from contract & necessary action to be taken against the contractor.
- Malba/ Garbage are littering on central verge, which are supposed to be maintained green.
- Kerb Stone found broken near Lal Sai Marg.
- Grill found damaged.

- Tree-Guard found tilted.
- Plantation work required on central verge.
- Excess earth lying on central verge near R K Furniture to be leveled.
- Tree-Guard broken to be removed from central verge near Gambhir Furniture.
- Building rubbish lying near Royal Furniture.
- Loose earth, broken tiles in central verge near New Classic Furniture.
- Malba lying near Grover Mittai Wala.
- Cement Concrete Block lying in central verge in front of Pankaj Traders.
- Encroachment on footpath near Najafgarh Road to be removed.
- At Tilak Nagar Bus Stand, footpath found broken to be repaired.

## **Vedic Marg**

- Tree which felled on the road during the storm few days back has yet to been removed.
- Malba lying opposite Ahuja Caterer.
- Building material dumped opp. UB-I, fine should be imposed.
- Bricks found stacked near Saifi Furniture, fine should be imposed.
- Marble pieces lying near Batra Property, fine should be imposed.
- Near Bhola creation, building rubbish required to be removed.
- Near Apna Health Centre, Main Hole Cover found broken.
- Near Prajapati/ Vodafone (exide), Kerb stone fallen on kerb channel.
- manhole cover broken near B.S. Motors.
- Near creative media- sand/ building material dumped, fine should be imposed.

### Goswami Tulsi Das Marg

- Near MCD School, building materials found stacked, fine should be imposed.
- Near MCD Park kerb stone to be repaired.
- Near Delite Enterprises, drain cover found broken.
- Footpath/ kerb channel required to be cleaned.
- Hari Nagar junction point to be maintained properly.
- Opp. Shanky Auto (Amit Nursing Home) drain cover to be placed properly.
- Plantation work is required on central verge.
- T-Guard to be placed properly.
- Central verge to be repaired near Gol Chakkar (DDU Hospital).
- Pruning of brushes/ shrubs required.
- manhole cover to be fitted properly in various locations.
- Near Aggarwal stones, unauthorised parking of vehicles.
- Near Vikrant place, stacked in bricks to be removed, fine should be imposed.

#### Rajouri Apartment Road

- After desilting, manhole cover (slippers) have been provided but found lot of gaps to be placed properly.
- Near Khera Automobiles, opp. Stacked in bricks on road site to be found, <u>fine should be imposed</u>.
- Near Petrol Pump (Bharat Petroleum)- footpath found broken to be repaired.
- Near Durga properties & Motors, Malba/ Garbage lying on footpath.

# Saheed Mangal Pandey Marg.

At starting point drain broken to be repaired.

# Kulwant Singh Sethi Marg.

- In between bloom/ South India, malba lying to be removed.
- Bell mouth blocked to be removed near Radhika Beauty Parlor.
- Drain cover not placed, cleaning kerb channel/ bell mouth required.

### Dharam Marg.

- At starting point, footpath tiles broken & manhole cover missing.
- Near DDA Park/ S.K.V.- Sand found stacking on footpath.
- Near Zarish Boutique- Malba lying on footpath, fine should be imposed.
- Opp. Arya Samaj Media, central verge, footpath required to be repaired.

### Gurudwara Road

Potholes required to be repaired near Mandir. Sand lying on footpath to be removed.

Superintending Engineer (West) and Executive Engineer (West) Road-1 to make sure that works are taken on fast track mode and take immediate necessary action for properly securing / covering of nallah, manhole covers within 7 days of issue of this letter and submit the action taken report.

Chief Engineer
PWD North Zone

# Copy to:

- 1. Pr. Chief Engineer (Maint.), PWD (GNCTD), New Delhi for information please.
- 2. SE (West), PWD (GNCTD), New Delhi for submission of consolidated ATR.
- 3. Director (Hort.), PWD (GNCTD), New Delhi for information.
- 4. EE (Elect.)-West, PWD (GNCTD), New Delhi for submission of ATR.
- 5. EE (West) Road-1, PWD (GNCTD), New Delhi for submission of ATR.
- 6. Dy. Director (Hort.), North, PWD (GNCTD), New Delhi for submission of ATR.

Executive Engineer (Plg.)