अधीक्षण अभियन्ता
केन्द्रीय एवं नई दिल्ली परिमंडल
लोक निर्माण विभाग,
राष्ट्रीय राजधानी क्षेत्र, दिल्ली सरकार,
भैंरो रोड टी—जंकशन, रिंग रोड,
नियर प्रगति पावर स्टेशन,
नई दिल्ली—110002
फोन न:—23378613/14



E-mail ID : sepwddelhicnd@gmail.com

Superintending Engineer

Central & New Delhi Circle
Public Works Department
Govt. of NCT of Delhi,
Bhairon Road T-Junction, Ring Road,
Near Pragati Power Station,
New Delhi-110002

Phone No.: 23378613 / 14

Date: 27-09-2017

No. 23(15)/SE/C&ND/PWD/2017-18/

INSPECTION NOTE

CE (East) carried out inspection on 23.09.2017 of area around Raj Ghat as function is to be held on 02.10.2017 in which high dignitories will participate. Following officers were present in the inspection :-

4401

- 1) Sh. Mukesh Kumar, SE (C&ND).
- 2) Sh. Anil Trehan EE(C&ND) Road.
- 3) Sh. Sanjay Verma, EE(E), DHC/ND.
- 4) Sh. Vijay Kumar, DDH (East) and feild staff.

In the inspection, following directions were given :-

(A) Main gate of Raj Ghat, Ring Road

- Road gully chamber in front of main gate of Raj Ghat should be repaired.
- 2. DBC on service road, footpath and drain repair should be carried out before 02 10 2017.
- Kaccha portion on the side of service road Grass paver may be provided.

(B) Kisan Ghat Road

- 1. Area of rumbled strip should be increased.
- 2. Damaged cobble stone and footpath should be repaired.
- 3. In the central verge, ground cover should be increased by Horticulture Unit.
- 4. Plantation be done to increase greenery.
- 5. Sign board provided at the entry of Kisan Ghat Road from Raj Ghat is not visible and information is also incorrect. The board should be placed at the visible location with the correct information.
- Pedestrian sign board should be provided at the zebra crossing.

(C) Raj Ghat intersection

- Accesibility should be increased on the footpath for the specially abled persons. At zebra crossing, cut may be made in the central verge for smooth walking.
- Service Road near main gate, Raj Ghat Footpath should be extended as discussed at site.
- 3. Miscellaneous Footpath, drains, toe-wall, gully chamber etc. at the main gate of Raj Ghat should be improved for giving aesthetic look keeping that foreign dignitaries visit the area.

(मुकेश कुमार) अधीक्षण अभियन्ता

प्रतिलिपि प्रेषित:-

- 1. The CE (East) M, PWD, 3rd floor, MSO Bldg., New Delhi-110002.
- 2. The EE (C&ND) Road Divn. (M-413), PWD, Bhairon road T-Junction, New Delhi. for compliance.
- 3. The EE, (DHC/ND) Elect. Divn. (M-451), PWD, Delhi-110054. for compliance.
- 4. The DDH Divn.(East) (M-214), PWD, G.S. Mihar Bhoaj Vatika, NH-24, Nizamuddin Bridge, New Delhi-110091. for compliance.

5. Guard file.

ी अधीक्षण अभियन्ता