

<p>अधीक्षण अभियन्ता केन्द्रीय एवं नई दिल्ली परिमंडल लोक निर्माण विभाग, राष्ट्रीय राजधानी क्षेत्र, दिल्ली सरकार, भैरो रोड टी-जंक्शन, रिंग रोड, नियर प्रगति पावर स्टेशन, नई दिल्ली-110002 फोन नं.-23378613 / 14</p>	 E-mail ID : sepwddelhicnd@gmail.com	<p>Superintending Engineer Central & New Delhi Circle Public Works Department Govt. of NCT of Delhi, Bhairon Road T-Junction, Ring Road, Near Pragati Power Station, New Delhi-110002 Phone No.: 23378613 / 14</p>
---	--	---

No. 23(15)/SE/C&ND/PWD/2017-18/

4804

Date: 23-10-2017

24

INSPECTION NOTE


Sub: Inspection and Meeting undertaken by E-in-C on 23.10.2017 reg. I.P. Flyover etc.
E-in-C, PWD held Inspection of I.P. Marg, I.P. Flyover, Ring Road (I.P. Flyover to Hanuman Setu), Ring Road Bypass, DDU Marg, Minto road, Asaf Ali Road and BSZ Marg on 23.10.2017. After the inspection, a meeting was also held by E-in-C. Inspection and meeting was attended by following officers:-

- 1) Sh. U.C. Mishra, CE (East).
- 2) Sh. Mukesh Kumar, SE (C&ND).
- 3) Sh. Vijay Kumar, SE (East).
- 4) Sh. Anil Trehan, EE(C&ND) Road.
- 5) Sh. Iqbal Singh, EE(East) Road.
- 6) Sh. Rajeev Lochan, EE(SRD-I).
- 7) Sh. Vijay Kumar, DDH(East).
- 8) Sh. Sanjay Verma, EE(E), DHC&ND/Central (M-451).

In the meeting and inspection, following directions were given:-


1. Beautification of area below I.P. Flyover is to be completed within 15 days as LG is to visit the area.
2. Work is to be undertaken on emergent basis including Civil, Electrical and Horticulture works; progress to be monitored on daily basis (All SEs).
3. Existing street scraping work below I.P. Flyover should be repaired wherever required. Gap filling may be provided in the Horticulture Work. Anti carbonation paint should be done under the flyover in the first phase.
4. An unauthorised temple is there below I.P. Flyover. Matter should be taken up with Religious Committee for its removal.
5. Pump House and JE Office at I.P. Flyover – Unserviceable material should be removed and stored material should be shifted. Footpath, building etc. should be repaired and painted properly. Complete area is to be developed with green features. The Pump house & the JE office should be integrated with the developed area.
6. I.P. Police Station – Unauthorised vehicles are parking on the road. Matter may be taken up with police for their removal.
7. Horticulture work needs to be improved from I.P. Flyover to Red Fort. Marry Gold plant may be provided on both sides of this Road.
8. Minto Road to Asaf Ali Road – Road is in bad condition.
9. Round about at Asaf Ali Road – A fountain or any other beautification work may be provided to beautify the area.
10. Malba on Asaf Ali Road – Matter may be taken up with North MCD.

11. Island near ISBT – The area may be provided with iron grill/RCC grill.
12. E-in-C directed that 50% work should be completed within 1 week. The site will be inspected by E-in-C after 1 week for review of work.
13. Individual SEs shall be the nodal officer for the development works to be done under their jurisdiction.


(मुकेश कुमार)
अधीक्षण अभियन्ता

प्रतिलिपि प्रेषित:-

1. The E-in-C, PWD, 12th floor, MSO Bldg., New Delhi-110002.
2. The Pr. CE (M), PWD, 9th floor, MSO Bldg., New Delhi-110002.
3. The CE (East), PWD, 3rd floor, MSO Bldg., New Delhi-110002.
4. The SE (East), PWD, C-218, Delhi Secretariat, I.P.Estate, New Delhi-110002.
5. The SE (Proj.), PWD, Lok Nayak Setu, Downstream Western Yamuna Bank, I.P.Estate, New Delhi.
6. The EE, (C&ND) Road Divn. (M-413), PWD, New Delhi-110002.
7. The DDH Divn. (M-214), PWD, G.S. Mihar Bhoaj Vatika, NH-24, Nizamuddin Bridge, New Delhi-110091.
8. The EE, (DHC/ND) Elect. Divn. (M-451), PWD, Ground Floor, MSO Bldg., Delhi-110054.
9. 23(23)/SE/C&ND/PWD/2017-18/
10. Guard file.


अधीक्षण अभियन्ता