

Phone: 011-22486228 Fax: 011-22488226

E-Mail: pwdcirclem21@yahoo.co.in

CONTRACTOR OF THE PARTY OF THE

Office of Superintending Engineer PWD Circle (NE) M 2nd. Nizamuddin Bridge Eastern Approach, Delhi-91.

दिनांक: 30.01.2018

द्वतीय निजामुकीन सेतु पूर्वी छोर, दिल्ली-91

कार्यालय अधीक्षण अभियंता

लो.नि.वि. परिमंडल(उ०पूर्व) एम

संः 23(Inspection)/लो०नि०वि०परि०(उ०पू०)एम/ 3) प्

Inspection Note

Inspection of North East Road was carried out on 27.01.2018 by the undersign. It was attended by the following officers:-

- 1) Sh. Devraj, EE (NE) Road
- 2) Sh. G.S. Meena, ADH (NE)

During the inspection, following directions were given:

- Pruning in general is required along the main roads. ADH to take action. He was also directed to remove abandoned/useless planters provided on the central verge of main road.
- 2) Epoxy paint needs to be done on the pipe of sign board.
- Pedestal of sign board/street pole needs to be painted.
- 4) At many places loose kerb stone and damaged footpath was seen, these needs to be repaired on priority.
- 5) Pump House at Drain No. 1 Sump well needs desilting. The pumps are also not in operation. EE Electrical, Sh. A.R. Chandekar to take urgent steps for the desilting and utilisation of pumps for the watering.
- 6) CC Road near Bhajanpura needs to be repaired. Letter may be written to CRRI for consultancy in this regard.

ATR in respect of above may be submitted by 05.02.2018.

(मुकेश कुमार) अधीक्षण अभियन्ता

प्रतिलिपि प्रेषितः-

1- The CE (East) M, PWD, 3rd floor, MSO Bldg., New Delhi-110002.

2- The EE, NE Road Division(M-213), PWD, Near IT Park, Shastri Park, Delhi-110053.

3- The EE (E) East Electrical Division (M 253), PWD, 2nd level, C Wing, Delhi Secretariat, New Delhi – 110002.

4- The DDH Divn. (M-214), PWD, G.S. Mihar Bhoaj Vatika, NH-24, Nizamuddin Bridge, New Delhi-110091.

5- The ADH (NE), PWD, G.S. Mihar Bhoaj Vatika, NH-24, Nizamuddin Bridge, New Delhi-110091.

6- Guard file.

अधीक्षण अभियन्ता