

<p>अधीक्षण अभियन्ता केन्द्रीय एवं नई दिल्ली परिमंडल लोक निर्माण विभाग, राष्ट्रीय राजधानी क्षेत्र, दिल्ली सरकार, भैरो रोड टी-जंक्शन, रिंग रोड, नियर प्रगति पावर स्टेशन, नई दिल्ली-110002 फोन नं.-23378613/14</p>	<p style="text-align: center;">दिल्ली सरकार</p>  <p style="text-align: center;">E-mail ID :sepwddelhicnd@gmail.com</p>	<p>Superintending Engineer Central & New Delhi Circle Public Works Department Govt. of NCT of Delhi, Bhairon Road T-Junction, Ring Road, Near Pragati Power Station, New Delhi-110002 Phone No.: 23378613 / 14</p>
---	--	--

No. 23(15)/SE/C&ND/PWD/2017-18/

607

Date: 09-02-2018

Inspection Note


University Campus was inspected on 01.02.2018 by the undersign along with Sh. Vipin Tiwari, OSD to V.C, Delhi University. Inspection was attended by the following officers:-

- 1) Sh. Rajiv Khare, AE (C&ND) Road.
- 2) Sh. S.K. Kalra, AE (C&ND) Electrical.
- 3) Sh. Shyam Singh, ADH

During the inspection, following observations were made:-

- 1) Shreya Mishra Marg – OSD mentioned that light is insufficient on this road. Due to trees, proper light is not available at the ground. It was proposed to provide double bracket on the existing street pole for better illumination. Action: EE(E)
- 2) GTB Road – Kerb channel have not been repaired. Footpath is broken in front of V.C House. Action: EE(Road)
- 3) OSD requested for removal of encroachment by taking the matter with STF/MCD. Action: EE(Road)
- 4) Road marking needs improvement as it has become black at number of places. OSD requested for coble stone flooring in front of college gates for safe pedestrian movement. EE (Road) to make estimate in this regard for obtaining A/E & E/S. Action: EE(Road)
- 5) Chatra Marg – OSD requested for development of this road as Model Road with proper lighting, greening, road marking and civil works. Action: EE(Road), DDH, EE (E).
- 6) At the entry and exit of footpath, proper ramp should be provided. Whenever length of footpath is more then 100 M, ramp/approach to footpath should also be provided in the middle of footpath. Action: EE(Road)
- 7) Some abandoned bolts were seen in the road/footpath which may be removed. OSD requested to provide solar studs, spring post, delineators, bollard on the roads for improvement. Action: EE(Road)
- 8) Tilted pole was noted at University Road (Stephen College staff quarter gate). Action: EE(E)
- 9) OSD observed that manhole cover/slabs are generally projecting out from the footpath which is inconvenient to physically challenged persons. He requested for providing smooth manhole covers at footpath level. University Road – Footpath needs to be repaired. Action: EE(Road).

- 10) Bus stop at University Road – Steep ramp has been provided which may be reduced. Action: EE(Road)
- 11) University Road – OSD requested to make University Road as Model Road on account of heavy pedestrian traffic. Action: EE(Road), DDH, EE (E)
- 12) Campus Road joining Mall Road – Proper Road geometry should be provided for smooth flow of traffic. Action: EE(Road)


(मुकेश कुमार)
अधीक्षण अभियन्ता

प्रतिलिपि प्रेषित:-

1. The CE (East), PWD, 3rd floor, MSO Bldg., New Delhi-110002.
2. Sh. Vipin Tiwari, OSD to V.C, University of Delhi, Equal Opportunity Cell, Faculty of Arts, University of Delhi, Delhi-110007.
3. The EE, C&ND (M-413), PWD, Bhairon Road T-Jn., Ring Road, New Delhi-110002 – He is to give ATR by 20.02.2018.
4. The EE (C&ND) Elect. Divn. (M-351), PWD, Old Sectt., Room No. 185, Delhi-110054 – He is to give ATR by 20.02.2018.
5. The DDH Divn. (M-214), PWD, G.S. Mihar Bhoaj Vatika, NH-24, Nizamuddin Bridge, New Delhi-110091 – For urgent action.
6. The ADH, PWD, Horticulture Sub-Div. East-2, Ground Floor, MSO Bldg., New Delhi – For urgent action.
7. Guard file.


अधीक्षण अभियन्ता