

By Hand/Speed Post/E-Mail

<p>अधीक्षण अभियन्ता केन्द्रीय एवं नई दिल्ली परिमंडल लोक निर्माण विभाग, राष्ट्रीय राजधानी क्षेत्र, दिल्ली सरकार, भैंसो रोड टी-जंक्शन, रिंग रोड, नियर प्रगति पावर स्टेशन, नई दिल्ली-110002 फोन नं.-23378613 / 14</p>	<p></p> <p></p> <p>E-mail ID :sepwddelhicnd@gmail.com</p>	<p>Superintending Engineer Central & New Delhi Circle Public Works Department Govt. of NCT of Delhi, Bhairon Road T-Junction, Ring Road, Near Pragati Power Station, New Delhi-110002 Phone No.: 23378613 / 14</p>
--	---	---

No. 23(15)/SE/C&ND/PWD/2017-18/

907

Date: 28-02-2018

सेवा में,

कार्यपालक अभियंता,
लो.नि.वि., के.एवं.न.दि.सड़क मंडल (एम-413),
नई दिल्ली-110002

विषय : **Inspection of works near I.P. Metro Station etc.**

Works being undertaken near I.P. Metro Station was inspected by me on 22.02.2018. During the inspection, following deficiencies have been observed:-

- 1) Rectangle paver block are being used instead of square one.
- 2) The paver block provided are seemed to be used one as its edges are broken in general.
- 3) Which brand of paver block are being used may be intimated by EE/AE w.r.t conditions of agreement.
- 4) Proper curing is not being done as no date has been mentioned.
- 5) Strength of plaster is very weak as it is easily coming out.
- 6) Work is stopped for the last many days. No hindrance should be given to the contractor.

Following observations are also made:

- 1) Firoz Shah Kotla Road near the main entry gate of Firoz Shah Kotla Fort – Road is damaged. It may be repaired urgently.
- 2) I.P. Flyover – At expansion joint, road repair has not been done properly as jerks are felt while driving on flyover.

(मुकेश कुमार)
अधीक्षण अभियन्ता

प्रतिलिपि प्रेषित:-

1. The AE, (C&ND) Road Division (Sub-Division-3), PWD, Bhairon Road T-junction, Ring Road, New Delhi-110002 – For necessary action.
2. Guard file.

अधीक्षण अभियन्ता