

<p><b>अधीक्षण अभियन्ता</b> केंद्रीय एवं नई दिल्ली परिमंडल लोक निर्माण विभाग, राष्ट्रीय राजधानी क्षेत्र, दिल्ली सरकार, भैंसो रोड टी-जंक्शन, रिंग रोड, नियर प्रगति पावर स्टेशन, नई दिल्ली-110002 फोन नं.-23378613/14</p>	<p></p> <p></p> <p>E-mail ID :sepwddelhicnd@gmail.com</p>	<p><b>Superintending Engineer</b> Central &amp; New Delhi Circle Public Works Department Govt. of NCT of Delhi, Bhairon Road T-Junction, Ring Road, Near Pragati Power Station, New Delhi-110002 Phone No.: 23378613 / 14</p>
--	---	---

No. 23(15)/SE/C&amp;ND/PWD/2017-18/ 761

Date: 19-02-2018

सेवा में,

कार्यपालक अभियन्ता,  
लो.नि.वि., के.एवं.न.दि.सड़क मंडल (एम-413),  
नई दिल्ली-110002

**विषय : Court Road, Civil Lines – repair of footpath etc.**

Inspection of Court Road near LG Secretariat was carried out on 19.02.2018 along with Sh. Vinod Garg, AE and Sh. Kuwar Pal Singh, JE. During the inspection, following directions were given:-

- 1) Footpath and kerb stone needs repair at number of places.
- 2) Connectivity of tactile is disrupted at many places. It may be ensured that tactile continuity is made.
- 3) Ramp to footpath be made wherever missing. Ramp should also be made at the junction/zebra crossing.
- 4) Boundary wall and grill along the footpath is broken at many places. Missing boundary wall and grill may be provided as discussed at site.
- 5) Kerb stone may be painted black & white.
- 6) Kerb channel which are depressed may be filled with CC.
- 7) CC Road is damaged at some places. This may be repaired.
- 8) Missing signboard and road furniture may also be provided.
- 9) EE (E) to check the street light on these roads.
- 10) Pruning is required on this stretch. AD(H) to take necessary action.

(मुकेश कुमार)  
अधीक्षण अभियन्ता

प्रतिलिपि प्रेषित:-

1. The CE (East), PWD, 3<sup>rd</sup> floor, MSO Bldg., New Delhi-110002.
2. The EE, (DHC/ND) Elect. Divn. (M-451), PWD, Ground Floor, MSO Bldg., Delhi-110054.
3. The AE, (C&ND) Road Division (Sub-Division-3), PWD, Bhairon Road T-junction, Ring Road, New Delhi-110002.
4. The AD(H), PWD, Horticulture Sub-Div. East-2, Ground Floor, MSO Bldg., New Delhi
4. Guard file.

अधीक्षण अभियन्ता