

<p>अधीक्षण अभियन्ता केन्द्रीय एवं नई दिल्ली परिमंडल लोक निर्माण विभाग, राष्ट्रीय राजधानी क्षेत्र, दिल्ली सरकार, भैरो रोड टी-जंक्शन, रिंग रोड, नियर प्रगति पावर स्टेशन, नई दिल्ली-110002 फोन नं.-23378613/14</p>	<p>दिल्ली सरकार  E-mail ID :sepwddelhicnd@gmail.com</p>	<p>Superintending Engineer Central & New Delhi Circle Public Works Department Govt. of NCT of Delhi, Bhairon Road T-Junction, Ring Road, Near Pragati Power Station, New Delhi-110002 Phone No.: 23378613 / 14</p>
---	--	--

No. 23(23,15)/SE/C&ND/PWD/2017-18/ 718

Date: 16-02-2018

Sub: Meeting held at V.C. Office, DU on 15.02.2018 relating to accessibility of footpath at University Campus and Inspection thereof.

A meeting was held on 15.02.2018 in the V.C. Office relating to accessibility of footpath to physically challenged persons in pursuant to Court directions. The meeting was attended by the following officers:-

- 1) Commissioner, North DMC
- 2) Registrar, DU
- 3) CE (East), PWD
- 4) OSD to V.C, DU
- 5) DCP, North Delhi
- 6) SE, C&ND Circle, PWD
- 7) SE, North MCD
- 8) Officers from DTL

In the meeting, following directions were given:-

- 1) License to kiosk have been given by MCD. Unauthorised kiosk may be removed by MCD. Kiosk which are hindering movement of pedestrians should be relocated. Kiosk which has violated license conditions, should be sealed.
- 2) Public toilet should be constructed by North MCD as per the location selected by Delhi University. NOC to be given by PWD in this regard to MCD. OSD, Sh. Vipin Tiwari requested for CCTV on the roads. Delhi Police/PWD to take necessary action in this regard. Proper signages may be provided in the University Roads.
- 3) Accesibility Audit of University Road has been done by PWD.
- 4) Bus stand has been provided by DTS. Bus stands should be user friendly to physically challenged persons. Advertising board have been provided across the footpath which may be placed parallel to avoid any hinderence to pedestrians.
- 5) Before any work is undertaken by DTS, it should obtain NOC from PWD.

Following the meeting, inspection was carried out. In the inspection including earlier ones, following directions were given:-

A) Mall Road from Timarpur Crossing to University Road

S.No.	Observation	Target Date of PWD
1.	Orange colour bollards to be provided on every crossing in central verge for vehicular safety.	31.03.2018

2.	Central verge is broken at places. Broken kerb stone needs to be replaced. RCC central verge may be provided in place of precast kerb stone where damage to kerb stone is frequent. Delineators may also be provided.	31.03.2018
3.	Kachcha portion beyond footpath and upto boundary of building is shabby, it needs to be developed. Horticulture and Civil work needs to be done.	31.03.2018
4.	Tactile to be provided on footpath. Bus stands to be made accessible by providing ramp for physically challenged persons.	31.03.2018
5.	Cycle track is broken at many places, it needs repair with micro concrete and top surface should be finished with thermoplastic high friction surface. JE & AE may see the sample provided at Shyama Prasad Mukherjee Marg.	31.03.2018
6.	Grass pavers provided around tree may be removed & small size kerb stone may be provided around planter.	31.03.2018
7.	At University Road turn, RCC drain covers are placed in haphazard manner. These drain covers should be fixed systematically.	31.03.2018
8.	Manholes frames are found broken which should be repaired/replaced. Old pedestal (2 Nos.) for advertisement needs to be removed. Bolts above the ground level at footpath should be cut.	31.03.2018
9.	Continuity of footpath to be maintained on adjoining roads including tactile.	31.03.2018
10.	Tiles broken/missing at bus stops may be intimated to DTS for repair.	31.03.2018

B) University Road

S.No.	Observation	Target Date of PWD
1.	Stalls have been located at the footpath which are causing inconvenience to pedestrians. These stalls need to be relocated/removed.	Pertain to North MCD
2.	Advertisement board provided across the footpath should be relocated along footpath.	Pertain to DTL
3.	Slope provided on the footpath for accessibility is steep, this may be rectified.	31.03.2018
4.	Bus stop marking has not been done by PWD.	28.02.2018
5.	OSD, Sh. Vipin Tiwari, requested for reduction in the height of bus stop platform.	Pertain to DTL
6.	Bollards be painted as per approved colour scheme.	31.03.2018
7.	Ramps may be provided for access to footpath at interval of 150 metre and at entry/exit of footpath.	31.03.2018
8.	Tactile tile to be provided continuously. (Location Bunglow No. 4).	31.03.2018
9.	At gates, quartzite flooring may be provided matching to footpath level with tactile tile. (Location Sir Sankar Lal Hall Guest House & Bonta Park Gate).	31.03.2018
10.	Abandoned poles are lying on footpath which may be removed (Action: EE(Elect.) M-351). At junction of G.C.Narang Marg, ramps to be provided. Black top surface is found worn-out towards Jublee Hall Road which may be repaired.	31.03.2018

11.	Ramps to be provided to footpath at zebra crossings.	31.03.2018
12.	Access to main gate of V.C. Office from footpath needs continuity.	31.03.2018

C) Shri Ram Road. (From Chaubhurja Chowk to Malka Ganj Petrol Pump)

S.No.	Observation	Target Date of PWD
1.	On carriage way, loose aggregate is lying which may be removed.	20.02.2018
2.	Strengthening is required to carriage way.	31.03.2018
3.	Gate of Shri Ram Institute to be made accesible.	31.03.2018
4.	There is no accessibility to footpath at Bonta Park side. Access to footpath to be made at a regular interval of 150 metre.	31.03.2018

D) Sudhir Bose Marg

S.No.	Observation	Target Date of PWD
1.	Tactile have been provided in general. Continuity of tactile to be ensured. Footpath found broken at many places. Gap between footpath and boundary wall to be made pucca as greenery is not possible.	31.03.2018
2.	At St. Stephan college, footpath to be made accessible. Manhole covers at two or three places are found 6" higher than footpath. (Location between Hindu College to junction of Chhatra Marg).	31.03.2018
3.	At Junction of Chhatra Marg, footpath to be made accessible at zebra crossing.	31.03.2018

E) Chhatra Marg

S.No.	Observation	Target Date of PWD
1.	Portion between boundary wall and footpath should be made pucca by providing paver block.	28.02.2018
2.	Food stall has been provided on the footpath which is causing unauthorised parking.	Pertain to North MCD
3.	An unauthorised gate has ben opened by a private person. Footpath on this portion has been damaged, it was decided to repair the footpath and to provide bollard in this portion of footpath.	28.02.2018
4.	CC Channel should be repaired by filling concrete. (Near V.C. house).	28.02.2018
5.	On cycle track, 6mm thick colour thermoplastic high friction surface may be provided.	30.04.2018
6.	Continuity of tactile to be maintained.	31.03.2018
7.	Ramps to be provided between gate and footpath.	31.03.2018

F) Shreya Mishra Marg

S.No.	Observation	Target Date of PWD
1.	Food stall has encroached a large area which is unauthorised.	Pertain to North MCD
2.	Footpath needs to be repaired.	31.03.2018
3.	Temporary shops have been allowed on the footpath. There is no space for pedestrians. MCD should look at them.	Pertain to North MCD

4.	Bus stop demarcation is to be done.	28.02.2018
5.	C.C.Channel to be provided.	31.03.2018
6.	At gate of Patel Chest, ramps to be provided.	31.03.2018
7.	Tactile tile to be made continuous.	31.03.2018
8.	At MCD dust bin, footpath corner is shabby, need to be improved.	31.03.2018

G) GTB Road

S.No.	Observation	Target Date of PWD
1.	Kiosk has been allowed at the footpath by MCD.	Pertain to North MCD
2.	Footpath is damaged near Office of OSD to V.C, Sh. Vipin Tiwari.	31.03.2018
3.	Opposite Shri Ram College, bus bay needs to be provided for proper bus parking.	31.03.2018
4.	At the bus stop, unauthorised parking of cars is there which is causing traffic jam.	Pertain to Traffic Police
5.	Footpath of GTB Road is to be made accessible and user friendly for physically challenged persons with tactile.	31.03.2018

H) G.C. Narang Marg

S.No.	Observation	Target Date of PWD
1.	Footpath needs to be repaired. Slope of ramp provided to footpath are not convenient. Road needs repair at some places.	Pertain to North MCD

It is intimated that PWD is taking action on the area pertaining to its jurisdiction. For the matter pertaining to other departments, necessary action may be taken by University authorities.

(मुकेश कुमार)
अधीक्षण अभियन्ता

प्रतिलिपि प्रेषित:-

1. The CE (East), PWD, 3rd floor, MSO Bldg., New Delhi-110002.
2. Sh. Vipin Tiwari, OSD to V.C, University of Delhi, Equal Opportunity Cell, Faculty of Arts, University of Delhi, Delhi-110007.
3. The EE, C&ND (M-413), PWD, Bhairon Road T-Jn., Ring Road, New Delhi-110002.
4. The EE (C&ND) Elect. Divn. (M-351), PWD, Old Sectt., Room No. 185, Delhi-110054.
5. The DDH Divn. (M-214), PWD, G.S. Mihar Bhoaj Vatika, NH-24, Nizamuddin Bridge, New Delhi-110091.
6. The ADH, PWD, Horticulture Sub-Div. East-2, Ground Floor, MSO Bldg., New Delhi-110002.
7. Guard file.

अधीक्षण अभियन्ता