

By Hand/Speed Post/E-Mail

<p>अधीक्षण अभियन्ता केन्द्रीय एवं नई दिल्ली परिमंडल लोक निर्माण विभाग, राष्ट्रीय राजधानी क्षेत्र, दिल्ली सरकार, भैंसो रोड टी-जंक्शन, रिंग रोड, नियर प्रगति पावर स्टेशन, नई दिल्ली-110002 फोन नं.-23378613/14</p>	<p></p> <p></p> <p>E-mail ID :sepwddelhicnd@gmail.com</p>	<p>Superintending Engineer Central & New Delhi Circle Public Works Department Govt. of NCT of Delhi, Bhairon Road T-Junction, Ring Road, Near Pragati Power Station, New Delhi-110002 Phone No.: 23378613 / 14</p>
--	---	--

No. 23(15)/SE/C&ND/PWD/2018-19/ 1806

Date: 03-05-2018

Inspection Note

Inspection of main Burari Road was carried out by undersign on 01.05.2018 along with Sh. Yadwinder Singh, EE (C&ND Road) and Sh. Rajat Kant, AE (C&ND Road). During the inspection, following directions were given:-

- EE to carry out field density check of DBM/DBC executed on Main Burari Road.
- At the start of Main Burari Road near Transport Authority, there is a gap of 3-4 mtr between drain and ROW limit. This area may be encroached upon by public in future. The existing drain is also not proper as circular manholes are at long interval. Hence, it would be proper to shift the drain towards end of ROW. On the opposite side, drain is missing in approx. 400 mtr length which may be constructed.
- At 3-4 locations on Main Burari Road, there are big pot holes. CC patch repair may be done wherever there is water logging problem and road has been damaged on account of this.
- Desilting work is in progress. At a few places, heaps of silt have been seen which may be removed as these are causing dust pollution.

प्रतिलिपि प्रेषित:-

1. The Pr. CE (M), PWD, 12th Floor, MSO Building, New Delhi-110002.
2. The EE, C&ND (M-413), PWD, Bhairon Road T-Jn., Ring Road, New Delhi-110002.
3. The EE (C&ND) Elect. Divn.(M-351), PWD, Old Sectt., Room No.185, Delhi-110054.
4. The DDH Divn. (M-214), PWD, G.S. Mihar Bhoaj Vatika, NH-24, Nizamuddin Bridge, New Delhi-110091.
5. Guard file.

(मुकेश कुमार)
अधीक्षण अभियन्ता

अधीक्षण अभियन्ता