



सं. 23(QC)/लो0नि0वि0/अनु0परि0(पूर्व)/ 1719

दिनांक: 29.08.2019

**Sub: Inspection of East Road Maint. Sub Divn. M-2123.**

The site of Sub Divn. M-2123 (Section 1 & 2) under East Road Maint. Divn. M-212 inspected alongwith Executive Engineer, Assistant Engineer and Junior Engineers on 22.08.2019. The following observations were found during the inspection.

The following documents were reviewed:

- Inspection Register.
- Hindrance Register.
- Site Order Book.
- MAS Register.
- Log Book of JCB.
- Log Book of Pocklane.
- Pumps Register.

Both the Section has maintained the registers of disposal of silt in which disposal slips have been pasted.

The total quantity of silt disposed for both the sections as given by Assistant Engineer concerned on 23.08.2019 is as under:

|           |  |
|-----------|--|
| Section-1 | Quantity of silt disposed. 6215.435 tonne. |
| Section-2 | Quantity of silt disposed. 4284.81 tonne.  |

During review of MAS Register, it was observed that rectangular RCC covers has been procured. EE to send his comments on this. EE also give reason for using pocklane machine for the work.

During inspection of desitling work, it was observed that at places, excavated silt has not been removed. Field staff may take immediate action and to check entire area where such type of silt is lying for immediate removal.

Executive Engineer may submit the report for the above observations to this office.

अधीक्षण अभियंता (पूर्व) एम

प्रतिलिपि (सूचनार्थ हेतु प्रेषित):-

- मुख्य अभियंता (पूर्व), लोनिवि अनुरक्षण अंचल, दि.स. तृतीय तल, एम.एस.ओ. भवन, नई दिल्ली।
- कार्यपालक अभियन्ता, लो.नि.वि. सड़क अनु0 मं0 (पूर्व)/एम 212, रमेश पार्क, नजदीक शकरपुर पुलिस स्टेशन, दिल्ली।
- वेबसाइट WIMS.
- गार्ड फाइल।

अधीक्षण अभियंता (पूर्व) एम