



सं. 23(QC)/लो0नि0वि0/अनु0परि0(पूर्व)/ 1718

दिनांक: 29.08.2019

Sub: Inspection of East Road Maint. Sub Divn. M-2124.

The site of Sub Divn. M-2124 under East Road Maint. Divn. M-212 inspected alongwith Executive Engineer and Assistant Engineer on 22.08.2019. The following observations were found during the inspection.

The following documents were reviewed:

- Cement Register.
- Hindrance Register.
- Site Order Book.
- MAS Register.

Only one major work i.e. "Providing barricading aspect in between Service Road and Shahdara drain in U.P. Link Road" was inspected. The work has not been started at site; however, fabrication of MS Grill work was in progress for the work. Steel weight register and sample of steel members checked.

During discussion, Executive Engineer told that there is very less work load in this Sub Divn. and some part of the roads of this Sub Divn. will be handed over to NHAI in future.

Executive Engineer was directed to prepare redistribution of sites among the Sub Divisions for approval by the competent authority.

अधीक्षण अभियन्ता (पूर्व) एम

प्रतिलिपि (सूचनार्थ हेतु प्रेषित):-

- मुख्य अभियन्ता (पूर्व), लोनिवि अनुरक्षण अंचल, दि.स. तृतीय तल, एम.एस.ओ. भवन, नई दिल्ली।
- कार्यपालक अभियन्ता, लो.नि.वि. सड़क अनु0 मं0 (पूर्व)/एम 212, रमेश पार्क, नजदीक शकरपुर पुलिस स्टेशन, दिल्ली।
- वेबसाइट WIMS.
- गार्ड फाइल।

अधीक्षण अभियन्ता (पूर्व) एम