



सं. 23(QC)/लो0नि0वि0 / अनु0परि0(पूर्व)/ 2569

दिनांक: 29.11.2019

Sub: Inspection of work under East Buidling Maint. Divn. M-221.

Inspection was carried out for the work of Staff Room in Khajoori Khas School, Delhi by the undersigned on 27.11.2019 alongiwith EE M-221, AE, JEs and agency of the work. The following observations were observed during the inspection:-

1. Fixing of flush door shutters is not proper. EE to check fittings of the door / window shutters and take necessary remedial measures.
2. Granite stone provided in Kitchen portion also not as per specification. EE to check thickness of the Granite stone and measurements may also be checked as per nomenclature of the item.
3. Table has been provided in the Staff room with stainless steel frame and particle board. EE to check the quality of the materials and all the mandatory tests should be carried out.
4. EE also check the overall quality of the materials and work as per nomenclature of the item and specifications.
5. EE to give a certificate that the site has been handed over to all the concerned Principals in which Schools the work has been executed.
6. Executive Engineer has not submitted the ATR for the inspection notes given vide letter of even No. No. 1602 dt. 14.08.2019, 1703 dt. 28.08.2019 and No. 1722 dt. 29.08.2019.

Executive Engineer to comply all the observations of the Inpsection notes.

अधीक्षण अभियंता (पूर्व) एम

प्रतिलिपि (सूचनार्थ हेतु प्रेषित):-

1. मुख्य अभियंता (पूर्व), लोनिवि अनुरक्षण अंचल, दि.स. तृतीय तल, एम.एस.ओ. भवन, नई दिल्ली।
2. कार्यपालक अभियन्ता, लो.नि.वि. भवन अनु0 मं0 (पूर्व)/एम 221, दिल्ली सचिवालय, नई दिल्ली।
3. वेबसाइट WIMS.
4. अधीक्षण अभियंता गार्ड फाइल।
5. गार्ड फाइल।

अधीक्षण अभियंता (पूर्व) एम