

राष्ट्रीय राजधानी क्षेत्र दिल्ली सरकार

GOVT. OF NATIONAL CAPITAL TERRITORY OF DELHI

कार्यालय अधीक्षण अभियन्ता

लो.नि.वि. अनुरक्षण परिमंडल (पूर्व)

दिल्ली सचिवालय, दूसरा तल, सी-218, नई दिल्ली 110002

दूरभाष: 011-23392194, फैक्स: 011-23392191



Office of Superintending Engineer

PWD Maintenance Circle (East)

Delhi Secretariat, 2nd Level, C-218,

IP Estate, New Delhi-110 002.

E-mail: sepwdelhim22@gmail.com

सं 23(निरिक्षण)/लो0नि0वि0/अनु0परि0 (पूर्व)/ 693

दिनांक: 18.06.2020

कार्य:- Inspection in respect of working of sewer pumps under jurisdiction of North-East Circle.

In reference to the office order issued by Dy. Director-I, O/o Pr. CE (M), PWD vide No. 23(37)/Pr. CE(M)/PWD/2020/1130 dt. 15.06.2020, the pumping stations of North-East Circle were inspected by SE (East)M on 17.06.2020 at 10:00 AM. The following were present.

PWD

1. Sh. S.K. Dey AE (Elect.), M-2511
2. Sh. C.L. Meena JE (Elect.) M-2511

The status report is as under:

S. No.	Location	DG Set	Maintained by Agency with Mob. No.	Capacity of Pumps	Qty. of Pumps	Status of Pumps (working or not)
1	Harsh Vihar	250 KVA (Greaves) -1 Nos Working)	M/S A.K. Electric Work (9990990239)	75 HP	1	Working
				150 HP	1	Not Working
				100 HP	4	3 Nos Working 1 Nos not Working
2	Dividing Road Yamuna Vihar	250 KVA (Greaves) -1 Nos Working	M/S A.K. Electric Work (9990990239)	75 HP	3	Working
				40 HP	1	Working
				30 HP	1	Working
				100 HP	2	Working
3	S.B.S Yamuna Vihar	200 KVA (Kirloskar)- 1 Nos (Not Working)	M/S A.K. Electric Work (9990990239)	100 HP	1	Not Working
				150 HP	1	Not Working
				75 HP	4	3 Nos Working 1 No. Not Working
4	MIG flat Ioni Road	250 KVA (Greaves) -1 Nos and 250 KVA (Kirloskar) -1 No (Not Working)	M/S A.K. Electric Work (9990990239)	150 HP	1	Not Working
				75 HP	3	2 No. Working 1 Nos not Working
				100 HP	3	2 Nos Working 1 No. Not Working
5	Gokul Puri	DG Set not available	M/S A.K. Electric Work (9990990239)	75 HP	1	Working
				submersible 20 HP	2	2 Nos Not Working

6	West of Loni Road (Drain no-1)	200 KVA (Greaves) – 1 Nos (Not Working)	M/S A.K. Electric Work (9990990239)	75 HP	2	Working
				40 HP	1	Not Working
7	C-12 Yamuna Vihar	250 KVA (Kirloskar) – 1 Nos Working	M/S A.K. Electric Work (9990990239)	40 HP	2	1 No. Working 1 No. not Working
				75 HP	2	Working
				100 HP (New)	2	Not Working
8	C-5 Yamuna Vihar	82.5 KVA (Kirloskar) (Working)	M/S A.K. Electric Work (9990990239)	40 HP	2	Only 1 No. Working 1 No. Not Working
				25 HP	1	Working
				100 HP	1	Working (leakage)
				28 BHP	1	Working
9	Ghamdi Pusta Road	125 KVA (Kirloskar) 1 Nos (Working)	M/S A.K. Electric Work (9990990239)	40 HP	2	Working
				75 HP	1	Working
10	Ghamdi Gaon	250 KVA (Greaves) – 1 Nos Working	M/S A.K. Electric Work (9990990239)	75 HP	4	1 Nos Working 3 Nos not Working
				100 HP	1	1 No. not Working
11	Loni Golchakkar	160 KVA (Kirloskar) Damaged	M/S A.K. Electric Work (9990990239)	75 HP	2	2 Nos Working But leakage in delivery pipe line
12	Bhajan pura MKt	125 KVA (Cummins) -1 Nos Working	M/S A.K. Electric Work (9990990239)	75 HP	2	1 No Working and 1 No. not Working
				25 HP	1	Not Working
13	Gagan Cinema	DG Set not available	M/S A.K. Electric Work (9990990239)	40 HP	2	Working
				75 HP	1	Working
				28 BHP	1	Not Working

EE (Elect.) is requested to ensure the compliance of observations made above.

अधीक्षण अभियंता (पूर्व) एम

प्रतिलिपि (सूचनार्थ एवं आवश्यक कार्यवाही हेतु प्रेषित):-

1. प्रधान मुख्य अभियंता, लोनिवि अनुरक्षण अंचल, तृतीय तल, एम.एस.ओ. भवन, नई दिल्ली।
2. अधीक्षण अभियंता, लो.नि.वि., उत्तर-पूर्व अनु० परि०/एम-21, द्वितीय निजामुद्दीन पुल, एन.एच.-24, बाईपास, दिल्ली-110091.
3. कार्यपालक अभियंता (वैद्युत), लो०नि०वि० वै०अनु० मंडल/एम-251, तल-4, एम.एस.ओ. भवन, नई दिल्ली।
4. अधीक्षण अभियंता गार्ड फाइल।
5. गार्ड फाइल।

अधीक्षण अभियंता (पूर्व) एम