

राष्ट्रीय राजधानी क्षेत्र दिल्ली सरकार
GOVT. OF NATIONAL CAPITAL TERRITORY OF DELHI

कार्यालय अधीक्षण अभियन्ता
लो.नि.वि. अनुरक्षण परिमंडल (पूर्व)
दिल्ली सचिवालय, दूसरा तल, सी-218, नई दिल्ली 110002
दूरभाष: 011-23392194, फैक्स: 011-23392191



Office of Superintending Engineer
PWD Maintenance Circle (East)
Delhi Secretariat, 2nd Level, C-218,
IP Estate, New Delhi-110 002.
E-mail: sepwddelhim22@gmail.com

सं. 23(निरीक्षण)/लो0नि0वि0 / अनु0परि0(पूर्व)/ 891

दिनांक: 27.07.2020

सेवा में,

कार्यपालक अभियन्ता,
लो.नि.वि. सड़क अनु0 मं0 (पूर्व)/एम 212,
रमेश पार्क, निकट शकरपुर थाना,
दिल्ली-110092

विषय:- Inspection of works of desilting of Drains.

The inspection of the works for desilting of drains under Divn. M-212 was conducted on 13.07.2020 alongwith you and your AEs & JEs. During the inspection, it was found that desilting Malba is still lying near the drains and it seems that no action has been taken for removal of malba.

Lot of complaints are being received from PWD Control room and on Whatsapp also which have been forwarded to you. You are again directed to remove all the malba without further delay and compliance may be sent to this office within 3 days.

अधीक्षण अभियन्ता (पूर्व) एम

प्रतिलिपि (सूचनार्थ हेतु प्रेषित):-

1. मुख्य अभियन्ता (पूर्व) एम, लोनिवि, अनुरक्षण अंचल, तृतीय तल, एम.एस.ओ. भवन, नई दिल्ली।
2. अधीक्षण अभियन्ता (पूर्व) एम गार्ड फाइल।
3. गार्ड फाइल।

अधीक्षण अभियन्ता (पूर्व) एम