

## अधीक्षण अभियंता

पलाईओवर परियोजना परिगंडल एफ −1, लो0 नि0 वि0 (दिल्ली सरकार) मुकरबा चौक जी0 टी0 करनाल रोड, दिल्ली−33

ईमेल: cpmpwddelhif1@gmail.com



पत्र संख्या 23(123)/एफ1/लो०नि०वि०/2023-हि./ 3

दिनांक: 28 7 23

निरीक्षण नोट

Name of work: Construction of conventional Bus Depot No. I & II on ground floor at

Sector A-1, A-4, Narela, Delhi.

Agreement No. 01/EE/FPD/F-14/PWD/2021-22

Agency: M/s P.K. Gupta & Co.

The inspection of the above work was carried out by the Superintending Engineer, F-1, PWD, GNCTD on 24.07.2023. The following were present:

PWD Side:

Shri Rajan Mogha, Superintending Engineer, F-1

Shri Devbrat Singh, Executive Engineer F-14

Shri Hemant Singh Patel, AEE F-142

Shri Tarun Garg, Authorized Signatory

Contractor Side:

Shri Deepak Chauhan, Site Engineer

Shri Viresh Dabas, Site Engineer

During the inspection, the following points were discussed: -

 The Finishing of the Admin building and Restroom building is in progress. The agency is directed to expedite the work. (Action: - Agency & EE and AEE PWD)

 Preparation of Subgrade, and column erection of workshop block is in progress and balance work needs to be expedited. (Action: - Agency & EE/ AEE PWD)

3. The target for the completion of work as given by the Transport Department is 30<sup>th</sup> September 2023. But as per the site visit, it appears that the progress is far behind the schedule. The agency is directed to expedite the work and submit revised program chart. (Action: - Agency & EE/ AEE PWD)

4. It was directed that the team to work with all safety precautions and avoid any lapses. Responsibility of any lapse shall be of executing agency. Directions issued by Secretariat in this regard must be followed in letter and spirit. [Action- Agency, EE/ AEE/ AE PWD]

अधीक्षण अभियंता

Copy to :-

1. The Chief Engineer (Flyover), PWD, 4th Floor, MSO Building, New Delhi.

 The Executive Engineer, F-14, PWD, Mukarba Chowk, Delhi. You are directed to convey the directions for agency by letters under your signature. Paste a copy of the inspection note in the inspection register. Submit the ATR within 7 days of the issue of this note.

3. The Assistant Executive Engineer, F-142, PWD, Delhi. You are directed to ensure compliance of above directions at site & submit ATR within 7 days of issue of this note.

 M/s P.K. Gupta & Co., 1<sup>st</sup> Floor, Plot No. 10, LSC-11, Metro Plaza, Sector-7, Rohini, North West Delhi-110086, Email- pkg01977@gmail.com for compliance.