



राष्ट्रीय राजधानी क्षेत्र, दिल्ली सरकार  
लोक निर्माण विभाग  
अधीक्षण अभियंता  
फ्लाईओवर-5

रिंग रोड फ्लाईओवर के नीचे, विपरीत आई0 जी0 स्टेडियम गेट नं0 9, नई दिल्ली-110002  
Under Ring Road Bypass Flyover, Opp. of IG Stadium Gate No.9, New Delhi-110002

Govt. of NCT of Delhi  
Public Works Department  
Superintending Engineer  
Flyover- 5



Email: cpmppwddelhi5@gmail.com

No. 23( Insp. )/PWD/SE/F-5/2023/105

dated 14.08.2023

### निरीक्षण नोट

An inspection of Additional half flyover at Sarai Kale Khan T- Junction was carried out by CE, Flyover on 14.08.2023 at 10:00 AM in presence of following:

#### **PWD Side:**

1. Sh. Rajan Premi Mogha, Superintending Engineer, F-5
2. Sh. Tej Singh Meena, EE, Flyover Project Division F-21, PWD, Delhi.
3. Sh. Anil Kumar Sharma, Assistant Engineer, F-212
4. Sh. Raj Kumar, Assistant Engineer, F-213

Following observations were made during the inspection:-

1. Progress of the flyover at site was reviewed and concern is expressed regarding progress of work & missing of targets. (Action:- Agency, EE, AE)
2. It was appraised by Sh Anil Sharma, AE that additional bracing is being incorporated as proposed by Designer. It shows that the earlier design was not checked properly. Action should be taken in this regard as per terms and conditions of the agreement. The action may be initiated by EE. (Action:- Executive Engineer, F-21)
3. Hon'ble PWD Minister has directed to complete the casting of balance slab by 18.08.2023 and completion of the entire flyover by 15.09.2023. These targets must be adhered. (Action:- Agency, EE, AE )
4. **Overall maintenance of site is poor. There are very few barricading boards. Malba is lying at site. Kerbs and footpath are in dilapidated condition. This work is on route of G20 summit and any laxity is unacceptable. Hence work is again advised that it is to be given utmost importance and in case of default action should be taken as per terms and conditions of the agreement. (Action:- Agency, EE, AE )**
5. Agency to adhere to all safety guidelines as per agreement, CPWD Works Manual, Safety codes, Good structural engineering practices & as issued by GNCTD vide No. 4(60)/23-

6. 24/PWD-II/Roads (CD No. 057742583)/1054-47 dated 11.07.2023. Responsibility of any violation shall be of executing agency & EE should take action as per guidelines for any violation. Agency should provide display signage's at site as per Sl. No. 1 of circular issued by GNCTD. (Action:- Agency, EE, AE)

14.8.23  
(राजन मोघा)  
अधीक्षण अभियंता

(क.प.)

**Copy to:**

1. **The Chief Engineer (Flyover)**, PWD, 4<sup>th</sup> Floor, MSO Bldg., New Delhi for information.
2. **The Executive Engineer (C)**, Flyover Project Division F-21, PWD (GNCTD), Under Ring Road Bypass Flyover, Opp. IG Stadium Gate No.9, New Delhi-110002. You are directed to convey the directions for agency by letters under your signature. Paste a copy of inspection note in inspection register. Submit the ATR within 7 days of issue of this note.
3. **M/s Gawar Construction Ltd.**, DSS-378, Sector 16-17, Hisar-125005 (Haryana) for information & compliance.

(क.प.)

14.8.23  
(राजन मोघा)  
अधीक्षण अभियंता