
	<p style="text-align: center;">अधीक्षण अभियंता फलाईओवर परियोजना परिमंडल एफ -1, लो0 नि0 वि0 (दिल्ली सरकार) मुकरबा चौक जी0 टी0 करनाल रोड, दिल्ली-33 ईमेल: cpmpwddelhi1@gmail.com</p>	
---	---	---

पत्र संख्या 23(94)/एफ1/लो0नि0वि0/2023-हि./ 553

दिनांक: 03/11/23

निरीक्षण नोट

Name of work: Construction of underpass by jack pushing pre-cast RCC boxes at outer ring road near Mukarba Chowk including construction of approach road from Badli Junction to Haiderpur Metro Station.

Agreement No. 04/EE/FPD/F14/PWD/2022-23

Agency: M/s Dharamraj Contracts India Private Limited

The site was inspected by undersigned on 03.11.2023, at 11:00 AM, of the above mentioned were. The following were present at site :-

PWD Side :	Shri Devbrat Singh, Executive Engineer F-14 Shri Hemant Singh Patel, AEE F-142 Shri Somesh Sarkar, AE (Elect.), F-132
Contractor Side:	Shri. Hemant Singh (Authorised signatory) Shri. Raj Kumar (Site Engineer)

During the inspection, the following points were discussed: -

1. IGL pipeline is still not shifted. It is to be brought to notice Chairman IGL and PWD Secretariat.
2. Irrigation department land payment is to be made. Executive Engineer to take up the matter at PWD Secretariat for early payment.
3. As per High Court guideline ramps are to be covered. Executive Engineer may check as per agreement provisions & sanctioned amount.
4. GRAP-III norms are implemented vide No. 1200 17/27/GRAP/2021/CAQM 02.11.2023 issued by Director (Technical) (Member & Convenor of Sub-Committee on GRAP) O/o Commission for Air Quality Management in National Capital Region and Adjoining Areas. It is directed that all measures are to taken to control air pollution. Responsibility of any violation shall be of executing agency & EE should take action as per guidelines for any violation.



5. Zero tolerance policy should be taken against the other agencies working in the stretch.
6. Fines are to be imposed by AE-in-charge for each violation against the contractor or other Govt. agencies without fail under intimation to undersigned.
7. Agency is directed to adhere to all safety guidelines as per agreement, CPWD Works Manual, Safety codes, Good structural engineering practices & circular issued by GNCTD vide No. 4(60)/23-24/PWD-II/Roads (CD No. 057742583)/1054-47 dated 11.07.2023. Responsibility of any violation shall be of executing agency & EE should take action as per guidelines for any violation.

OIL
11.11.23
(राजन मोघा)
अधीक्षण अभियंता

Copy to :-

1. The Chief Engineer (Flyover), PWD, 4th Floor, MSO Building, New Delhi.
- 2-3. The Executive Engineer, F-14 & F-13, PWD, Mukarba Chowk, Delhi. You are directed to convey the directions for the agency by letters under your signature. Paste a copy of the inspection note in the inspection register. Submit the ATR within 7 days of the issue of this note.
4. The Assistant Executive Engineer, F-142, PWD, Mukarba Chowk, Delhi. You are directed to ensure compliance with the above directions at the site.
5. Assistant Engineer (Elect.), F-132, PWD, Mukarba Chowk, Delhi. You are directed to ensure compliance with the above directions at the site.
6. M/s Dharamraj Contracts India Private Limited, Abhishek Plaza, 3rd Floor, Pocket-B, Mayur Vihar, Phase-II, New Delhi - 110091, Email- dharamraaj@rediffmail.com for compliance.

OIL
अधीक्षण अभियंता