





**North Delhi Municipal Corporation
Office of the Executive Engineer (M-I)RZ**



Subject:- W.P. (C) No. 104/2015 – Guru Hanuman Society of India Versus Govt. of NCT of Delhi & Ors. A public interest Litigation pertaining to speed breakers.

Ref. No. E-in-C/NDMC/2017-18/D-348 Dated: 25.09.2017



S. No.	Zone / Division	Date of Joint Inspection	Location of the speed breakers	Authorized / Unauthorized	Signages exists or not	Whether modified as per IRC guidelines	Pit holes / missing manholes (Identified under the survey)	Photographs taken (before and after action)	Remarks
1	Rohini (M-I) Division	25 October-2017	In front of H. No. 254, PKT-C-9, Sec-07, Rohini	Unauthorized	-	-	No		Unauthorized speed breaker removed
2	Rohini (M-I) Division	25 October-2017	In front of Radha swami centre H. No. 148, D-14, Sec-7, Rohini	Unauthorized	-	-	No		Unauthorized speed breaker removed


3	Rohini (M-I) Division	25 October- 2017	In front of 16/320, Sec-07, Rohini	Unauthorized	-	-	No		Unauthorized speed breaker removed
4	Rohini (M-I) Division	25 October- 2017	In front of 16/402, Sec-07, Rohini	Unauthorized	-	-	No		Unauthorized speed breaker removed
5	Rohini (M-I) Division	25 October- 2017	In front of 16/405, Sec-07, Rohini	Unauthorized	-	-	No		Unauthorized speed breaker removed

6	Rohini (M-I) Division	25 October-2017	Back side road of Hans Raj Gupta Hospital, Sec-07, Rohini	Unauthorized	-	-	No		Unauthorized speed breaker removed
7	Rohini (M-I) Division	27 October-2017	In front of Banshal Steel, A-1, Vijay Vihar Ph.-II	Unauthorized	-	-	No		Unauthorized speed breaker removed
8	Rohini (M-I) Division	27 October-2017	In front of Banshal coaching centre, A-10 Vijay Vihar Ph.-II	Unauthorized	-	-	No		Unauthorized speed breaker removed

9	Rohini (M-I) Division	27 October-2017	In front of Vaishno Mandir, A-16, Vijay Vihar Ph.-II	Unauthorized	-	-	No		Unauthorized speed breaker removed
10	Rohini (M-I) Division	27 October-2017	In front of Shop No. B5/142 Sec-05, Rohini near. Hanuman Mandir	Unauthorized	-	-	No		Unauthorized speed breaker removed

11	Rohini (M-I) Division	27 October-2017	In front of B-7/63, Sec-05, Rohini	Unauthorized	-	-	No		Unauthorized speed breaker removed
12	Rohini (M-I) Division	27 October-2017	In front of B-9/177, Sec-05, Rohini	Unauthorized	-	-	No		Unauthorized speed breaker removed
13	Rohini (M-I) Division	27 October-2017	In front of C-1/68, Sec-05, Rohini	Unauthorized	-	-	No		Unauthorized speed breaker removed

14	Rohini (M-I) Division	27 October-2017	In front of C-1/72, Sec-05, Rohini	Unauthorized	-	-	No		Unauthorized speed breaker removed
15	Rohini (M-I) Division	27 October-2017	In front of Westend Apartment B-8 Road, Sector-4, Rohini	Unauthorized	-	-	No		Unauthorized speed breaker removed

16	Rohini (M-I) Division	27 October- 2017	In front of AA-11, Hargovind Vihar, Sector-4, Rohini	Unauthorized	-	-	No		Unauthorized speed breaker removed
----	--------------------------	---------------------	---	--------------	---	---	----	--	--

Executive Engineer(M-I)RZ