

Details of Potholes, Open Manholes

As on 15.02.2018

Sl.No.	Sl.No. as per list	Name of the Road	Location	Potholes/M anholes	Civic Agency	Distt.	Present status as on 15.02.2018 (Repaired/ or not repaired)
1	177	Mathura Road, Ashram to Badarpur carriageway	Near NFC Red Light	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
2	178	Mathura Road.	Aali Village	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
3	179	Mathura Road.	Madanpur Khadar Red Light	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
4	180	Mathura Road.	Under Badarpur Flyover	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
5	181	Mathura Road.	Opp. HP Petrol Pump under Badarpur Flyover	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
6	182	Mathura Road.	Near Mohan Estate Metro Station	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
7	183	Mathura Road.	Near Metro Pillar No. 327-330	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
8	184	Mathura Road.	Under Sarita Vihar Station.	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
9	185	Mathura Road.	Near Tuglakabad Metro Station	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
10	186	Mathura Road.	Sarita Vihar Flyover	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
11	187	Road No. 13A	Kalindi Kunj Chowk	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
12	188	Road No. 13A	Near Living Style Mall	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
13	189	M.B. Road	Near Misthan Cafe Devli to Khanpur carriageway	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
14	190	M.B. Road	Tigri Red Light	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
15	191	M.B. Road	Near Khanpur Bus Stop	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
16	192	M.B. Road	Hamdard to Vayusenabad both side	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
17	198	Outer Ring Road	Near Gas Godown	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
18	199	Outer Ring Road	Near Savitri Flyover	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
19	200	Ring Road	Railway Over Bridge, Nehru Nagar, Ring Road (Ashram to Moolchand Carriageway)	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete

20	201	Ring Road	In front of Mother Dairy near Maharani Bagh Foot over Bridge (Ashram to Maharani Bagh Carriageway)	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
21	202	M.B. Road	Ratiya Marg Cut	Manhole	PWD	South-East	Repaired
22	204	M.B. Road	Vayusenabad to Hamdard (both carriageway)	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
23	205	Ravi Dass Marg	Ravi Das Marg MB road cut to Hanuman Mandir Gali No. 13	Potholes	PWD	South-East	Strengthening/Re-surfacing work complete
24	197	Rawta Daurala Road	Shubham Hair Dresser	Unauthorised	PWD	South-West	Repaired
25	206	Road No.37	Hastal	Unauthorised	PWD	South-West	Pertains to West Circle