

Pedestrian Accident Prone Zone-2018

SL. NO. As per List	Accident Prone Zone	Office	Status of Action Taken	Remarks
1/3	BHALSWA CHOWK	North Circle / Flyover	Location pertains to F-11	
2/4	MUKUNDPUR CHOWK	C&ND / North Circle / Flyover	Due to high speed of vehicles and negligence of road users. / Location pertains to F-11	
3/8	Mukarba Chowk	North / Flyover	Thermoplastic painting work done. CAT Eye, spring post, nose protection etc. provided on the road. Strengthening / Resurfacing work has been carried out. Further a Foot Over Bridge is under construction to be functional soon. Iron Grill provided in the central verge between Mukarba Chowk to Bhalswa by Flyover F-11	