

Black Spots Report (2018)

Sl. No.	Sl. No. as per list	Black Spot	Office	Remarks / ATR
1	3	Bhalswa Chowk	North Circle / F-11	Location pertains to F-11
2	4	Mukundpur Chowk	North Circle / F-11	Location pertains to F-11
3	5	Libaspur Stand	North Circle	Location pertains to NHAI
4	8	Mukarba Chowk	North Circle	Thermoplastic painting work done. CAT Eye, spring post, nose protection etc. provided on the road. Strengthening / Resurfacing work has been carried out. Further a Foot Over Bridge is under construction to be functional soon. Iron Grill provided in the central verge between Mukarba Chowk to Bhalswa by Flyover F-11