

## Pedestrian Accident Prone Zone-2018

SL. No.	SL. No. As per List	Accident Prone Zone	Office	Status of Action Taken
1	4	Libaspur Bus Stand	North Circle	Location pertains to NHAI
2	5	Bhalswa Chowk	North Circle	Location pertains to Flyover F-11
3	7	Prem Bari pull	North Circle	
4	11	SIRASPUR	North Circle	Location pertains to NHAI
5	13	Mukarba Chowk	North	Thermoplastic painting work done. CAT Eye, spring post, nose protection etc. provided on the road. Strengthening / Resurfacing work has been carried out. Further a Foot Over Bridge is under construction to be functional soon. Iron Grill provided in the central verge between Mukarba Chowk to Bhalswa by Flyover F-11
6	19	Azadpur Subzi Mandi	North Circle	Opening of central verge has been closed to avoid fatal accident of pedestrians.
7	26	Azadpur Chowk	North Circle	Railing has been fixed at Round about and opening in central verge has been closed. Speed calming devices i.e. Rumble strips, signages, road marking paint & Cat Eye's have been fixed.
8	30	Budhpur Ganda Nala / Hanuman Mandir Budhpur	North Circle	Location pertains to NHAI