

PEDESTRIAN ACCIDENT PRONE ZONE – 2017

S.NO	ACCIDENT_PRONE_ZONE	Office	STATUS OF ACTION TAKEN
1/2	BRITANNIA CHOWK	North-west Circle	Speed calming devices i.e. Rumble strips, signages, road marking paint have been fixed.
2/13	SAHSTRI NAGAR METRO STATION	North-west Circle	Speed calming devices i.e. Rumble strips, signages, road marking paint have been fixed.

ACCIDENT PRO

S.NO	S.No. as per list	ACCIDENT_PRONE_ZONE	Office
1	6	BRITANNIA CHOWK	North-west Circle
2	26	METRO STATION HAIDERPUR	North-west Circle
3	31	MANGOLPURI FLYOVER	North-west Circle
4	39	METRO STATION INDERLOK	North-west Circle
5	50	SANTOM HOSPITAL OUTER RING ROAD	North West
6	60	SAHSTRI NAGAR METRO STATION	North-west Circle
7	71	NEAR HALDI RAM WAZIRPUR	North-west Circle
8	96	WEST ENCLAVE RED LIGHT	North-west Circle
9	102	WAZIRPUR DEPOT	North-west Circle
10	123	HAIDER PUR	North-west Circle

ONE ZONE – 2017

STATUS OF ACTION TAKEN
Work related to safety measured has been done.
Cautionary boards and Glow studs provided, as a road safety measure and road marking done on this flyover for minimise the accidents.
Work related to safety measured has been done.
Table tops exist. U-Turn has been provided. Red light T-junction has been closed.
Work related to safety measured has been done.
Work related to safety measured has been done.
Work related to safety measured has been done.
Being examined with the Traffic Police.
Matter has been taken up with Northern Railway by PWD/Traffic Police to widen the ROB. No response has been received from Northern Railway, so far. Pertains to Railway.