

**PEDESTRIAN ACCIDENT PRONE ZONE – 2017**

<b>S.NO</b>	<b>S.No. as per list</b>	<b>ACCIDENT_PRONE_ZONE</b>	<b>Office</b>	<b>STATUS OF ACTION TAKEN</b>
<b>1</b>	<b>5</b>	METRO STATION MADIPUR	West Circle	
<b>2</b>	<b>16</b>	METRO STATION INDERLOK	West Circle	
<b>3</b>	<b>17</b>	BHARTI VIDHYAPEETH ROHTAK RD	West Circle	

**ACCIDENT PRONE ZONE – 2017**

S.NO	ACCIDENT_PRONE_ZONE	Office	STATUS OF ACTION TAKEN
11	METRO STATION MADIPUR	West Circle	Fresh road marking has been completed and provide the all cautionary & informatry sinages board and installed the nose protection devices. The estimate for fixing railing on divider has already been sent to higher authority for sanction .
16	PEERAGARHI CHOWK	West Circle	As per the direction of the traffic police the intersections at Peeragarhi Chowk has been modified as per feasibility of site. Zebra crossings all around the Peeragarhi Chowk has
18	PUNJABI BAGH CHOWK	West Circle	Road marking, cautionary & informatry signage board , nose protection device has already been provided. Traffic Police take action for regulating the traffic properly.
19	BHARTI VIDHYAPEETH ROHTAK RD	West Circle	
20	UDYOG NAGAR	West Circle	
42	KAKROLA DWARKA MORE	West Circle	Dense Carpeting over brocken cement concrete road under Dwarka Mor Metro Station provided for smooth movement of traffic. Railing on central verge is being repaired/ provided. Road marking, cautionary & informatry signage board has already been provided. Traffic Police take action for regulating the traffic properly.
47	RAJDHANI PARK	West Circle	MS grill has already been provided on central verge and footpath for pedestrian has been repaired. Traffic police is to take a action to regulate the heavy traffic properly which comes from the wrong side.
55	TIKRI KHURD BUS STAND	West Circle	As per traffic police main crossing at Tikri Border has been closed by DMRC and a U-Turn is being provided as per direction of the NGT to divert the heavy loaded traffic from the border at a short distance where the width of carriageway is adequate for movement of the traffic. All safety measures shall be provided by the DMRC.
68	UTTAM NAGAR	West Circle	
69	PANI KI TANKI NANGLOI	West Circle	Infront of Water Tank DJB has provided filling point for tankers which causes the overflow water on the road resulting to damaging the road continuously. DJB has agreed leakage of water line is to be repaired within a Week. Deep sewer excavation of Delhi Jal Board has also been carried out.
73	MOTI NAGAR FLYOVER	West Circle	Road marking, cautionary & informatry signage board , nose protection device has already been provided. Traffic Police take action for regulating the traffic properly. DJB pipeline is leaking heavily.
76	KIRARI MORE	West Circle	