

ACCIDENT PRONE ZONE – 2017

S.NO	S. No. as per list	ACCIDENT_PRONE_ZONE	Office	STATUS OF ACTION TAKEN	Remarks
1	1	MUKUNDPUR CHOWK	Flyover	Location pertains to F-11	As per report given by North Circle
2	2	JAHANGIR PURI BUS STAND OUTER RING ROAD	Flyover	Location pertains to F-11	
3	4	BHALSWA CHOWK	North Circle	Location pertains to F-11	
4	5	BURARI CHOWK	North Circle	Location pertains to F-11	
5	7	SIRASPUR	North Circle	Location pertains to F-11	

Pedestrian Accident Prone Zone-2018

SL. NO. As per List	Accident Prone Zone	Office	Status of Action Taken	Remarks
1/3	BHALSWA CHOWK	Flyover	Location pertains to F-11	As per report given by North Circle
2/4	MUKUNDPUR CHOWK	Flyover	Due to high speed of vehicles and negligence of road users. / Location pertains to F-11	As per report given by North Circle
3/8	Mukarba Chowk	North / Flyover	Thermoplastic painting work done. CAT Eye, spring post, nose protection etc. provided on the road. Strengthening / Resurfacing work has been carried out. Further a Foot Over Bridge is under construction to be functional soon. Iron Grill provided in the central verge between Mukarba Chowk to Bhalswa by Flyover F-11	As per report given by North Circle