

PEDESTRIAN ACCIDENT PRONE ZONE – 2017

S.NO	ACCIDENT_PRONE_ZONE	Office	STATUS OF ACTION TAKEN	Remarks
1/1	JAHANGIR PURI BUS STAND OUTER RING ROAD	North Circle / Flyover	Location pertains to F-11	As per report given by North Circle
2/3	MUKUNDPUR CHOWK	North Circle / Flyover	Location pertains to F-11	
3/4	SIRASPUR	North Circle / Flyover	Location pertains to F-11	
4/20	BHALSWA CHOWK	North Circle / Flyover	Location pertains to Flyover F-11	

Pedestrian Accident Prone Zone-2018

SL. NO. As per List	Accident Prone Zone	Office	Status of Action Taken	Remarks
1/5	Bhalswa Chowk	Flyover	Location pertains to Flyover F-11	As per report given by North Circle
2/13	Mukarba Chowk	North / Flyover	Thermoplastic painting work done. CAT Eyes, spring post, nose protection etc. provided on the road. Strengthening / Resurfacing work has been carried out. Further a Foot Over Bridge is under construction to be functional soon. Iron Grill provided in the central verge between Mukarba Chowk to Bhalswa by Flyover F-11	