

## **ACCIDENT PRONE ZONE – 2017**

| <b>S.NO</b> | <b>S.No. as per list</b> | <b>ACCIDENT_PRONE_ZONE</b>      | <b>Office</b>     | <b>STATUS OF ACTION TAKEN</b>  |
|-------------|--------------------------|---------------------------------|-------------------|--|
| 1           | 6                        | BRITANNIA CHOWK                 | North-west Circle |  |
| 2           | 26                       | METRO STATION HAIDERPUR         | North-west Circle | Work related to safety measured has been done.   |
| 3           | 31                       | MANGOLPURI FLYOVER              | North-west Circle | Cautionary boards and Glow studs provided, as a road safety measure and road marking done on this flyover for minimise the accidents.                                    |
| 4           | 39                       | METRO STATION INDERLOK          | North-west Circle | Work related to safety measured has been done.   |
| 5           | 50                       | SANTOM HOSPITAL OUTER RING ROAD | North West        | Table tops exist. U-Turn has been provided. Red light T-junction has been closed.  |
| 6           | 60                       | SAHSTRI NAGAR METRO STATION     | North-west Circle | Work related to safety measured has been done.   |
| 7           | 71                       | NEAR HALDI RAM WAZIRPUR         | North-west Circle | Work related to safety measured has been done.   |
| 8           | 96                       | WEST ENCLAVE RED LIGHT          | North-west Circle | Work related to safety measured has been done.   |
| 9           | 102                      | WAZIRPUR DEPOT                  | North-west Circle | Being examined with the Traffic Police.  |
| 10          | 123                      | HAIDER PUR                      | North-west Circle | Matter has been taken up with Northern Railway by PWD/Traffic Police to widen the ROB. No response has been received from Northern Railway, so far. Pertains to Railway. |

## Accident Prone Zone-2018

| SL. No. | SL. NO. As per List | Accident Prone Zone                 | Office            | Status of Action Taken  | Remarks                             |
|---------|---------------------|-------------------------------------|-------------------|---|-------------------------------------|
| 1       | 52                  | Wazir Pur Depot                     | North-west Circle | Being examined with the Traffic Police.   |                                     |
| 2       | 53                  | SANTOM HOSPITAL OUTER RING ROAD     | North West        | Table tops exist. U-Turn has been provided. Red light T-junction has been closed.       | Old Report                          |
| 3       | 55                  | Budhpur Ganda Nala / Hanuman Mandir | North West        |   |                                     |
| 4       | 58                  | Shastri Nagar Metro Station         | North West Circle | Pertains to North West Road I (North West Circle)                                       | As per report given by North Circle |
| 5       | 65                  | METRO STATION INDERLOK              | North-west Circle | Work related to safety measured has been done.  |                                     |
| 6       | 78                  | BRITANNIA CHOWK                     | North-west Circle | Speed calming devices i.e. Rumble strips, signages, road marking paint have been fixed. | Old Report                          |