

ACCIDENT PRONE ZONE – 2017

S.NO	S.No. as per list	ACCIDENT_PRONE_ZONE	Office	STATUS OF ACTION TAKEN
1	3	AZAD PUR CHOWK	North Circle	Speed calming devices i.e. Rumble strips, signages, road marking paint & Cat Eyes have been fixed.
2	8	SHANI MANDIR NH-1	North Circle	Location pertains to NHAI
3	12	MUKHARBA CHOWK	North Circle	Thermoplastic painting work done. CAT Eye, spring post, nose protection etc. provided on the road. Strengthening / Resurfacing work has been carried out.
4	23	PRAKASH VIHAR SHAHBAD DAIRY	North Circle	Location pertains to MCD / DDA
5	24	SGT NAGAR	North Circle	Location pertains to NHAI
6	25	SINGHU BORDER	North Circle	Location pertains to NHAI.
7	27	PRAHLAD PUR VILLAGE	North Circle	Location pertains to DDA.
8	35	PETROL PUMP RD NO 51	North Circle	Warning Sign Boards of "Accident Prone Area" & "Go Slow" has been installed at Road No.51 near Petrol Pump
9	37	ADARSH NAGAR	North Circle	Painting of zebra, red light, signages & bollards provided.
10	45	NANGLI POONA	North Circle	Pertains to NHAI
11	48	BAKOLI BUS STAND	North Circle	Pertains to NHAI
12	53	PREPAID BOOTH MUKHARBA CHOWK	North Circle	Signages provided and road marking work done
13	58	CNG PUMP / JAIN MANDIR NH1	North Circle	Pertains to NHAI
14	77	LIBASPUR BUS STAND	North Circle	Location pertains to NHAI
15	82	AZADPUR BUS TERMINAL	North Circle	Railing has been fixed at Round about and opening in the central verge has been closed.
16	113	SHAHBAD DAIRY	North Circle	Warning Sign Boards of "Accident Prone Area" has been provided and painting of Zebra crossing has been done.
17	121	SWAROOP NAGAR	North Circle	Location pertains to NHAI
18	125	AZADPUR SABJI MANDI	North Circle	Opening of central verge has been closed to avoid fatal accident of pedestrians.
19	138	KEVAL PARK ROAD NO. 51	North Circle	Speed calming devices at locations i.e. speed breakers, rumble strips, Cat Eyes & signage at Road No.51 from Azadpur Flyover to Mukundpur Chowk have been provided

Accident Prone Zone-2018

SL. No.	SL. NO. As per List	Accident Prone Zone	Office	Status of Action Taken	Remarks
1	5	LIBASPUR BUS STAND	North	Location pertains to NHAI	
2	8	Mukarba Chowk	North / Flyover	Thermoplastic painting work done. CAT Eye, spring post, nose protection etc. provided on the road. Strengthening / Resurfacing work has been carried out. Further a Foot Over Bridge is under construction to be functional soon. Iron Grill provided in the central verge between Mukarba Chowk to Bhalswa by Flyover F-11	
3	22	Swaroop Nagar	North Circle	Location pertains to NHAI	
4	26	Majlis Park Metro Station	North Circle	Permission / NOC has been given to DMRC for construction of Foot Over Bridge in front of Majlis Park Metro Station.	
5	28	SIRASPUR	North Circle	Location pertains to NHAI	
6	32	AZAD PUR CHOWK	North Circle	Railing has been fixed at Round about and opening in central verge has been closed.	
7	35	JAHANGIR PURI METRO STATION	North Circle	Signage at accident prone area and painting of Zebra crossing done.	
8	40	SHAHBAD DAIRY	North Circle	Signage at accident prone area has been provided and painting of Zebra crossing has also been completed.	
9	46	Singhola Village	North Circle	Pertains to NHAI	
10	50	Singhu Border	North Circle	Pertains to NHAI	
11	68	Azadpur Subzi Mandi	North Circle	Opening of central verge has been closed to avoid fatal accident of pedestrians.	
12	70	Prepaid Booth Mukarba Chowk	North Circle	Signages provided and road marking work done.	
13	89	Khampur Village	North Circle	Pertains to NHAI	
14	91	Sai baba Mandir NH-1	North Circle	Pertains to NHAI	