

Black Spots Report (2018)

Sl. No.	Sl. No. as per list	Black Spot	Office	Remarks / ATR
1	5	Libaspur Stand	North Circle	Location pertains to NHAI
2	8	Mukarba Chowk	North Circle	Thermoplastic painting work done. CAT Eyes, spring post, nose protection etc. provided on the road. Strengthening / Resurfacing work has been carried out. Further a Foot Over Bridge is under construction to be functional soon. Iron Grill provided in the central verge between Mukarba Chowk to Bhalswa by Flyover F-11 (Mukarba Chowk)