

PEDESTRIAN ACCIDENT PRONE ZONE – 2017

S.NO	ACCIDENT_PRONE_ZONE	Office	STATUS OF ACTION TAKEN
1/2	BRITANNIA CHOWK	North-west Circle	Speed calming devices i.e. Rumble strips, signages, road marking paint have been fixed.
2/13	SAHSTRI NAGAR METRO STATION	North-west Circle	Speed calming devices i.e. Rumble strips, signages, road marking paint have been fixed.

Pedestrian Accident Prone Zone-2018

SL. NO. As per List	Accident Prone Zone	Office	Status of Action Taken	Remarks
1/7	Prem Bari pull	North Circle	Location pertains to North West Road I (North West Circle)	As per report given by North Circle
2/32	SAHSTRI NAGAR METRO STATION	North-west Circle	Speed calming devices i.e. Rumble strips, signages, road marking paint have been fixed.	